



Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014) - Swan and Canning Rivers

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
SWAN	EV3/520	Middle Swan Reserve	2009-2014	112	920	D	11692	320	High	Rainfall	Collect 10 rainfall (24-48hrs) samples	Very poor	Red	5
SWAN	EV3/519	Ray Marshall Park (First Ave)	2009-2014	88	330	C	24000	140	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	12
BASSEDEAN	EV3/548	Point Reserve (Nth Jetty)	2011-2014	54	640	D	545	174	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) & stormwater samples	Very Poor	Red	12
BASSEDEAN	EV3/522	Sandy Beach Reserve	2009-2014	63	490	C	11720	522	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	12
BELMONT	EV3/517	Garvey Park (Fautleroy Ave)	2009-2014	75	390	C	1992	220	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	12
BELMONT	EV3/539	Cracknell Park (Riversdale Rd)	2009-2014	72	85	B	125	50	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
BELMONT	EV3/538	Belmont Park Beach (End Beach - Goodwood Pd)	2009-2014	71	135	B	202	65	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
BAYSWATER	EV3/523	Hind Reserve (Garratt Rd - Jetty)	2009-2014	70	65	B	95	43	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
BAYSWATER	EV3/541	East St Maylands Yacht Club	2009-2014	67	110	B	217	57	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
PERTH	PR3/022	Claisebrook	2011-2014	55	12	A	43	22	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
PERTH	PR3/023	Trinity	2011-2014	56	310	C	676	136	Outstanding		Provide DoH Sanitary Inspection Report	Fair (a)	Amber	12
PERTH	PR3/024	Point Fraser	2011-2014	57	160	B	180	70	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12



Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014) - Swan and Canning Rivers

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
PERTH	PR3/025	Barrack Jetty	2011-2014	57	36	A	79	32	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
PERTH	PR3/026	Mounts Bay Road	2011-2014	56	200	B	324	88	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
SOUTH PERTH	EV3/513	Coode St South Perth	2009-2014	87	260	C	404	106	Moderate - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	12
SOUTH PERTH	EV3/546	South Perth (Esplanade Beach)	2009-2014	102	125	B	185	61	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
SOUTH PERTH	EV3/512	Narrows Bridge	2009-2014	86	180	B	3657	97	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
SOUTH PERTH	EV3/537	Como Beach North	2009-2014	80	280	C	3102	196	Outstanding		Provide DoH Sanitary Inspection Report	Fair (a)	Amber	12
SOUTH PERTH	EV3/511	Como Beach Jetty	2009-2014	67	24	A	156	10	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
SOUTH PERTH	EV3/536	Como Beach South	2009-2014	80	110	B	537	53	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
CANNING	EV3/547	Clontarf Bay (Cadets)	2010-2014	76	440	C	623	157	Moderate - F/up	Rainfall	Collect 5-10 rainfall (24-48hrs) samples	Poor	Red	12
CANNING	EV3/542	Shelly Beach (Near Drain)	2009-2014	73	180	B	987	97	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) & stormwater samples	Fair (a)	Amber	12
MELVILLE	EV3/540	Deep Water Point Beach (Near Jetty)	2009-2014	73	30	A	86	23	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12



Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014) - Swan and Canning Rivers

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
MELVILLE	EV3/534	Waylen Bay (Scout Hall)	2009-2014	72	40	A	118	27	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
MELVILLE	EV3/507	Cunningham St (Applecross)	2009-2014	76	30	A	92	21	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
MELVILLE	EV3/533	Point Walter (Boat Ramps)	2009-2014	76	32	A	77	29	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12
MELVILLE	EV3/532	Point Walter (Kiosk)	2009-2014	75	65	B	131	41	Low	Stormwater	Provide DoH stormwater drain monitoring results	Good	Green	12
MELVILLE	EV3/505	Bicton Baths	2009-2014	75	30	A	52	31	Moderate - F/up	Stormwater	Provide DoH stormwater drain monitoring results	Good (a)	Green	12
SUBIACO	EV3/530	Hackett Dve Crawley (Tree)	2009-2014	73	115	B	191	59	Moderate - F/up	Rainfall	Collect 10 rainfall (24-48hrs) & stormwater samples	Good	Green	12
SUBIACO	EV3/528	Hackett Dve Crawley (Kiosk, Jetty)	2009-2014	73	165	B	352	79	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Fair (a)	Amber	12
SUBIACO	EV3/543	Abrahams Reserve Beach	2009-2014	73	45	B	117	30	Moderate - F/up	Rainfall	Collect 5-10 rainfall (24-48hrs) & stormwater samples	Good	Green	12
PEPPERMINT GROVE	EV3/503	Keane St Beach (50M S Irvine)	2009-2014	68	80	B	144	47	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	12
MOSMAN PARK	EV3/544	Johnston Street - Hill Tce Beach	2009-2014	72	5	A	32	17	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	5
EAST FREMANTLE	EV3/545	Preston Point - John Tonkin Park	2009-2014	43	16	A	51	22	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	12