



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|----------------------------|------------------------|----------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| Gascoyne Region | | | | | | | | | | | | | | | | |
| Carnarvon (Shire of) | Inlet | CN3/001 | Carnarvon Town Beach | -24.898049, 113.640697 | 1. Program | 2013-2018 | 32 | 165 | B | 2852 | 97 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Carnarvon (Shire of) | Inlet | CN3/003 | Facsine Beach | -24.883493, 113.65417 | 1. Program | 2011-2015 | 51 | 45 | B | 96 | 34 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Carnarvon (Shire of) | Inlet | CN3/004 | Baxter Park Beach | -24.89152, 113.654091 | 1. Program | 2011-2015 | 48 | 45 | B | 700 | 20 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Carnarvon (Shire of) | Inlet | CN3/005 | Yacht Club | -24.89233, 113.654028 | 1. Program | 2013-2015 | 33 | 30 | A | 140 | 12 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Carnarvon (Shire of) | Inlet | CN3/045 | Fascine Jetty | -24.884065, 113.653027 | 1. Program | 2013-2018 | 39 | 50 | B | 118 | 35 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Carnarvon (Shire of) | Ocean | CN3/046 | Pelican Point Beach | -24.897549, 113.638457 | 1. Program | 2013-2018 | 34 | 4 | A | 30 | 16 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Carnarvon (Shire of) | Harbour | CN3/043 | Boat Harbour Snapper Jetty | -24.898193, 113.65109 | 4. Active (Non-core) | 2013-2018 | 36 | 36 | A | 95 | 27 | Not Avail | Not Avail | Green | | 5 |
| Carnarvon (Shire of) | Harbour | CN3/044 | Boat Harbour Wharf | -24.899092, 113.650946 | 4. Active (Non-core) | 2011-2015 | 48 | 8 | A | 38 | 21 | Not Avail | Not Avail | Green | | 5 |
| Carnarvon (Shire of) | Inlet | CN3/002 | Carnarvon Town Beach (2) | -24.89784, 113.64085 | 4. Active (Non-core) | 2013-2018 | 35 | 20 | A | 63 | 19 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Carnarvon (Shire of) | Inlet | CN3/006 | Yacht Club Marina | -24.894711, 113.653688 | 4. Active (Non-core) | 2013-2015 | 33 | 16 | A | 48 | 25 | Not Avail | Not Avail | Green | | 5 |
| Carnarvon (Shire of) | Inlet | CN3/041 | Northwater DB Drive | -24.881972, 113.65414 | 4. Active (Non-core) | 2011-2015 | 43 | 95 | B | 226 | 51 | Not Avail | Not Avail | Green | | 5 |
| Carnarvon (Shire of) | Inlet | CN3/042 | Northwater Jaaga | -24.88268, 113.649727 | 4. Active (Non-core) | 2013-2018 | 34 | 95 | B | 396 | 46 | Not Avail | Not Avail | Green | | 5 |
| Carnarvon (Shire of) | River | CN3/047 | Chinamans Pool | -24.860979, 113.673522 | 4. Active (Non-core) | 2011-2015 | 32 | 720 | D | 1329 | 271 | Not Avail | Not Avail | Red | | 5 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|---|------------------------|---------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| Gascoyne Region ... | | | | | | | | | | | | | | | | |
| Exmouth (Shire of) | Canal | EX3/057 | Canal Nr Bridge Horwood Side | -21.954736, 114.135727 | 1. Program | 2013-2018 | 34 | 40 | A | 111 | 29 | Moderate | Good (a) | Green | Collect 5-10 stormwater drain samples | 13 |
| Exmouth (Shire of) / DoT | Harbour | EX3/050 | Small Boat Harbour - Boat Ramp | -21.955913, 114.13953 | 1. Program | 2013-2018 | 32 | 28 | A | 75 | 26 | Low | Very Good | Green | Annual SIR Review | 13 |
| Exmouth (Shire of) | Ocean | EX3/051 | Exmouth Town Beach | -21.945644, 114.140116 | 1. Program | 2013-2018 | 27 | 2 | A | 23 | 14 | Low | Very Good | Green | Annual SIR Review | 13 |
| Goldfields - Esperance Region | | | | | | | | | | | | | | | | |
| Esperance (Shire of) / DoT | Harbour | ES3/030 | Bandy Creek Harbour | -33.831938, 121.933446 | 1. Program | 2013-2018 | 53 | 200 | B | 700 | 91 | Moderate | Good | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Esperance (Shire of) | Ocean | ES3/031 | James St Groyne | -33.860941, 121.89603 | 1. Program | 2013-2018 | 52 | 90 | B | 189 | 51 | Moderate | Good | Green | Collect 5-10 stormwater drain samples | 13 |
| Esperance (Shire of) / Esperance Port Authority | Ocean | ES3/032 | Port Authority Beach | -33.867722, 121.895011 | 1. Program | 2013-2018 | 51 | 90 | B | 195 | 49 | Moderate | Good | Green | Collect 5-10 stormwater drain samples | 13 |
| Great Southern Region | | | | | | | | | | | | | | | | |
| Albany (City of) | Harbour | AC3/009 | Boatshed Beach - Princess Royal Harbour | -35.031225, 117.889195 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Albany (City of) | Inlet | AC3/007 | Emu Beach - Oyster Harbour | -34.996985, 117.947777 | 3. Proposed | 2014-2015 | 8 | 2200 | D | | 145 | Not Avail | Not Avail | Red | Provide DoH SIR | 13 |
| Albany (City of) | Ocean | AC3/010 | Frenchman Bay | -35.092244, 117.94883 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Albany (City of) | Ocean | AC3/032 | Ellen Cove (Jetty) - Middleton Beach | -35.025484, 117.918298 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|---|------------------------|----------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| Great Southern Region ... | | | | | | | | | | | | | | | | |
| Albany (City of) | Harbour | AC3/025 | Oyster Harbour - 6021173 - AOH1 - S - Middle | -34.983231, 117.955659 | 4. Active (Non-core) | | | | | | | Not Avail | Not Avail | | | 5 |
| Albany (City of) / DWER | Harbour | AC3/026 | Oyster Harbour - 6021174 - AOH2 - SE | -34.98291, 117.965439 | 4. Active (Non-core) | | | | | | | Not Avail | Not Avail | | | 5 |
| Albany (City of)/ DWER | Harbour | AC3/027 | Oyster Harbour - 6021260 - AOH12 - SW Yak Crk | -34.982958, 117.943254 | 4. Active (Non-core) | | | | | | | Not Avail | Not Avail | | | 5 |
| Albany (City of)/ DWER | Harbour | AC3/028 | Oyster Harbour - 6021176 - AOH4 - NW Bay Rd | -34.962303, 117.954409 | 4. Active (Non-core) | | | | | | | Not Avail | Not Avail | | | 5 |
| Albany (City of)/ DWER | Harbour | AC3/029 | Oyster Harbour - 6021177 - AOH5 - NW - Low Kg | -34.950692, 117.955238 | 4. Active (Non-core) | | | | | | | Not Avail | Not Avail | | | 5 |
| Albany (City of)/ DWER | River | AC3/030 | Oyster Harbour - 6021254 - AOH6 - NE - Kalg Rvr Bdg | -34.948953, 117.977734 | 4. Active (Non-core) | | | | | | | Not Avail | Not Avail | | | 5 |
| Albany (City of)/ DWER | River | AC3/031 | Lower Bridge - 6021063 - Lower King Rvr Bdg | -34.94397, 117.947702 | 4. Active (Non-core) | | | | | | | Not Avail | Not Avail | | | 5 |
| Cranbrook (Shire of) | Lake | CR3/001 | Nunijup Lake | -34.4054, 117.406573 | 3. Proposed | | | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48 hrs) samples | 13 |
| Cranbrook (Shire of) | Lake | CR3/002 | Lake Poorrarecup | -34.419673, 117.233831 | 3. Proposed | | | | | | | Low | Not Avail | Green | Annual SIR Review | 13 |
| Denmark (Shire of) | Inlet | DK3/051 | Wilson Inlet - Yacht Club Gazebo | -34.975896, 117.366096 | 1. Program | 2013-2018 | 21 | 85 | B | 323 | 41 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Denmark (Shire of) | Ocean | DK3/025 | Peaceful Bay - Ocean | -35.041714, 116.92976 | 1. Program | 2013-2018 | 29 | 50 | B | 167 | 27 | Moderate | Good | Green | Collect 5-10 stormwater drain samples | 13 |
| Denmark (Shire of) | Ocean | DK3/025A | Peaceful Bay - Ocean (South) | -35.042113, 116.929721 | 1. Program | 2013-2018 | 30 | 2 | A | 14 | 11 | Moderate | Good (a) | Green | Collect 5-10 stormwater drain samples | 13 |
| Denmark (Shire of) | Ocean | DK3/025B | Peaceful Bay - Ocean (North) | -35.041352, 116.929873 | 1. Program | 2013-2018 | 30 | 34 | A | 140 | 15 | Moderate | Good (a) | Green | Collect 5-10 stormwater drain samples | 13 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|--|------------------------|----------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| Great Southern Region ... | | | | | | | | | | | | | | | | |
| Denmark (Shire of) | Bore | DK3/035 | Peaceful Bay - Central Ave Bore | -35.039025, 116.926137 | 4. Active (Non-core) | 2013-2018 | 41 | | A | | 10 | Not Avail | Not Avail | Green | | 5 |
| Denmark (Shire of) | Bore | DK3/038 | Peaceful Bay - Fourth Ave Bore | -35.038081, 116.926452 | 4. Active (Non-core) | 2013-2018 | 42 | | A | | 10 | Not Avail | Not Avail | Green | | 5 |
| Denmark (Shire of) | Bore | DK3/039 | Peaceful Bay - Fith Ave Bore | -35.037803, 116.924256 | 4. Active (Non-core) | 2013-2018 | 41 | 90 | B | 700 | 19 | Not Avail | Not Avail | Green | | 5 |
| Denmark (Shire of) | Bore | DK3/040 | Peaceful Bay - Bore Tap Caravan Park | -35.040626, 116.927578 | 4. Active (Non-core) | 2013-2018 | 42 | 18 | A | 140 | 10 | Not Avail | Not Avail | Green | | 5 |
| Denmark (Shire of) | Creek | DK3/021 | Peaceful Bay - Supply Creek | -35.041304, 116.925934 | 4. Active (Non-core) | 2013-2018 | 41 | 3700 | D | 25934 | 2951 | Not Avail | Not Avail | Red | | 5 |
| Denmark (Shire of) | Creek | DK3/024 | Peaceful Bay - Creek/Drain | -35.041636, 116.929175 | 4. Active (Non-core) | 2013-2018 | 41 | 540 | D | 922 | 201 | Not Avail | Not Avail | Red | | 5 |
| Denmark (Shire of) | Drain | DK3/023 | Peaceful Bay Open Drain - Foot Bridge | -35.041127, 116.928611 | 4. Active (Non-core) | 2013-2018 | 42 | 820 | D | 965 | 247 | Not Avail | Not Avail | Red | | 5 |
| Denmark (Shire of) | Drain | DK3/026 | Peaceful Bay Open Drain - Peppermint Rd | -35.037608, 116.921235 | 4. Active (Non-core) | 2013-2018 | 9 | 1700 | D | 4082 | 695 | Not Avail | Not Avail | Red | | 5 |
| Denmark (Shire of) | Drain | DK3/027 | Peaceful Bay Drain - Cnr West Ave/Fourth Ave | -35.037982, 116.923731 | 4. Active (Non-core) | 2013-2018 | 13 | 560 | D | 673 | 181 | Not Avail | Not Avail | Red | | 5 |
| Denmark (Shire of) | Drain | DK3/028 | Peaceful Bay Drain - Cnr East Ave/Fourth Ave | -35.037566, 116.927596 | 4. Active (Non-core) | 2013-2018 | 11 | 2850 | D | 14432 | 1811 | Not Avail | Not Avail | Red | | 5 |
| Denmark (Shire of) | Drain | DK3/029 | Peaceful Bay Drain - Caravan Park | -35.04009, 116.929362 | 4. Active (Non-core) | 2013-2018 | 8 | 440 | C | 405 | 133 | Not Avail | Not Avail | Red | | 5 |
| Denmark (Shire of) | Drain | DK3/042 | Nornalup - Drain Outlet | -34.990902, 116.815937 | 4. Active (Non-core) | 2013-2018 | 41 | 480 | C | 900 | 190 | Not Avail | Not Avail | Amber | | 5 |
| Denmark (Shire of) | Reservoir | DK3/022 | Peaceful Bay - Water Supply Dam | -35.040871, 116.927578 | 4. Active (Non-core) | 2013-2018 | 42 | 1000 | D | 2938 | 460 | Not Avail | Not Avail | Red | | 5 |
| Denmark (Shire of) | Tap | DK3/031 | East Ave (Lot 163) - Garden Tap | -35.039597, 116.928095 | 4. Active (Non-core) | 2013-2018 | 42 | 105 | B | 216 | 56 | Not Avail | Not Avail | Amber | | 5 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|--|------------------------|------------------------|---------------|-------------|-------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|--|-------------------------------|
| Great Southern Region ... | | | | | | | | | | | | | | | | |
| Denmark (Shire of) | Tap | DK3/036 | Peaceful Bay - Third Ave (Lot 92) Garden Tap | -35.038736, 116.92496 | 4. Active (Non-core) | 2013-2018 | 42 | 50 | B | 131 | 33 | Not Avail | Not Avail | Green | | 5 |
| Denmark (Shire of) | Creek | DK3/052 | Creek - Inlet Drive Bridge 3 | -34.9739, 117.3653 | 5. Inactive (Non-core) | 2012-2013 | 13 | 520 | D | 586 | 164 | Not Avail | Not Avail | Red | | 0 |
| Denmark (Shire of) | Inlet | DK3/055 | Wilson Inlet - Springdale Beach 6 | -34.969435, 117.387766 | 5. Inactive (Non-core) | 2012-2013 | 25 | 100 | B | 333 | 52 | Not Avail | Not Avail | Green | Provide DoH SIR | 5 |
| Denmark (Shire of) | Inlet | DK3/050 | Wilson Inlet - Ocean Beach Caravan Park | -35.02107, 117.327082 | 6. Review | 2012-2014 | 26 | 45 | B | 700 | 10 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Denmark (Shire of) | Inlet | DK3/053 | Wilson Inlet - Rivermouth Caravan Park | -34.970279, 117.369053 | 6. Review | 2013-2018 | 21 | 210 | C | 405 | 93 | Not Avail | Not Avail | Amber | Provide DoH SIR | 13 |
| Denmark (Shire of) | River | DK3/054 | Denmark River - Berridge Park | -34.959994, 117.357211 | 6. Review | 2013-2018 | 21 | 1100 | D | 2086 | 403 | Not Avail | Not Avail | Red | Provide DoH SIR | 13 |
| Katanning (Shire of) | Lake | KT3/013 | Lake Ewlyamartup | -33.693108, 117.736472 | 3. Proposed | | | | | | | Moderate | Not Avail | Amber | Collect 10 stormwater, upstream riverine & rainfall (24-48hrs) samples | 13 |
| Kimberley Region | | | | | | | | | | | | | | | | |
| Broome (Shire of) | Ocean | BM3/070 | Gantheaume Point | -17.972379, 122.187052 | 2. New | 2017-2018 | 9 | 260 | C | 315 | 98 | Not Avail | Not Avail | Amber | Provide DoH SIR | 13 |
| Broome (Shire of) | Ocean | BM3/071 | Cable Beach | -17.931514, 122.209044 | 2. New | 2017-2018 | 10 | 390 | C | 856 | 168 | Not Avail | Not Avail | Amber | Provide DoH SIR | 13 |
| Broome (Shire of) | Ocean | BM3/073 | Town Beach Roebuck Bay | -17.971442, 122.235969 | 2. New | 2017-2018 | 12 | 430 | C | 484 | 141 | Not Avail | Not Avail | Amber | Provide DoH SIR | 13 |
| Broome (Shire of) | Ocean | BM3/074 | Streeters' Jetty Roebuck Bay | -17.953451, 122.24599 | 2. New | 2018 | 8 | 800 | D | 973 | 246 | Not Avail | Not Avail | Red | Provide DoH SIR | 13 |
| Broome (Shire of) / Broome Port Authority | Ocean | BM3/072 | Port Authority Beach | -18.001231, 122.209594 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|-----------------------------|------------------------|---------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| Kimberley Region ... | | | | | | | | | | | | | | | | |
| Halls Creek (Shire of) | Lake | HC3/002 | Lake Komaterpila | -18.346907, 127.823112 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Halls Creek (Shire of) | Pool | HC3/001 | Caroline Pool | -18.226293, 127.758536 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Halls Creek (Shire of) | River | HC3/003 | Palm Springs | -18.420166, 127.845376 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Halls Creek (Shire of) | Stream | HC3/004 | Sawpit Gorge | -18.424952, 127.820059 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Midwest Region | | | | | | | | | | | | | | | | |
| Greater Geraldton (City of) | Ocean | GE3/001 | Town Beach Jetty | -28.772771, 114.60733 | 1. Program | 2013-2018 | 32 | 2 | A | 12 | 11 | High | Good (a) | Green | Collect 5-10 stormwater drain samples | 13 |
| Greater Geraldton (City of) | Ocean | GE3/003 | Point Moore North | -28.782423, 114.577166 | 1. Program | 2013-2018 | 31 | 30 | A | 81 | 26 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Greater Geraldton (City of) | Ocean | GE3/005 | Separation Point | -28.78948, 114.59664 | 1. Program | 2012-2018 | 20 | 150 | B | 848 | 78 | Moderate | Good | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Greater Geraldton (City of) | Ocean | GE3/006 | Back Beach | -28.79514, 114.611337 | 1. Program | 2013-2018 | 31 | 30 | A | 140 | 14 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Greater Geraldton (City of) | Ocean | GE3/008 | Marina North | -28.763243, 114.614429 | 1. Program | 2013-2018 | 30 | 3 | A | 29 | 17 | Moderate | Good (a) | Green | Collect 5-10 stormwater drain samples | 13 |
| Greater Geraldton (City of) | Ocean | GE3/010 | Saint Georges | -28.745934, 114.617895 | 1. Program | 2013-2018 | 32 | 30 | A | 93 | 21 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Greater Geraldton (City of) | Ocean | GE3/012 | Sunset Beach - Triton Place | -28.721125, 114.6192 | 1. Program | 2013-2018 | 32 | 34 | A | 100 | 23 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Greater Geraldton (City of) | Ocean | GE3/021 | Pages Beach North | -28.776499, 114.583602 | 1. Program | 2013-2018 | 34 | 290 | C | 1705 | 170 | Moderate | Poor | Red | Collect 5-10 stormwater drain samples | 13 |
| Greater Geraldton (City of) | Ocean | GE3/022 | Tarcoola Beach | -28.81802, 114.62311 | 1. Program | 2013-2018 | 29 | 5 | A | 30 | 13 | Very Low | Very Good | Green | Annual SIR Review | 13 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|-----------------------|------------------------|---------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| Midwest Region ... | | | | | | | | | | | | | | | | |
| Greater Geraldton (City of) | Ocean | GE3/023 | Greenough Beach | -28.861882, 114.63482 | 1. Program | 2013-2018 | 29 | 9 | A | 38 | 12 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Greater Geraldton (City of) | Ocean | GE3/026 | Drummonds Cove | -28.670796, 114.611879 | 1. Program | 2011-2014 | 23 | 45 | B | 106 | 32 | Low | Good | Green | Annual SIR Review | 13 |
| Greater Geraldton (City of) | River | GE3/024 | Greenough River Mouth | -28.862921, 114.638199 | 1. Program | 2013-2018 | 33 | 160 | B | 244 | 73 | High | Fair (a) | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Greater Geraldton (City of) | River | GE3/025 | Ellendale Pool | -28.860916, 114.973733 | 1. Program | 2013-2018 | 33 | 340 | C | 384 | 118 | High | Poor | Red | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Irwin (Shire of) / DoT | Harbour | IR3/080 | Marina (Boat Ramp) | -29.274863, 114.91862 | 1. Program | 2011-2017 | 27 | 30 | A | 140 | 10 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Irwin (Shire of) | Ocean | IR3/001 | Nun's Pool | -29.261797, 114.920922 | 1. Program | 2011-2017 | 27 | 75 | B | 700 | 10 | Moderate | Good | Green | Collect 5-10 riverine & site samples | 13 |
| Irwin (Shire of) | Ocean | IR3/060 | South Beach | -29.283478, 114.919042 | 1. Program | 2011-2017 | 27 | 14 | A | 49 | 18 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Irwin (Shire of) | Ocean | IR3/070 | Granny's Beach | -29.271023, 114.92187 | 1. Program | 2011-2017 | 27 | 18 | A | 60 | 18 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Peel Region | | | | | | | | | | | | | | | | |
| Mandurah (City of) | Canal | MD3/330 | Hall Park | -32.533631, 115.716415 | 1. Program | 2013-2018 | 62 | 5 | A | 30 | 11 | Low | Very Good | Green* | Annual SIR Review | 5 |
| Mandurah (City of) | Canal | MD3/410 | North Port | -32.596808, 115.639226 | 1. Program | 2013-2018 | 62 | 45 | B | 122 | 29 | Moderate | Good | Green | Collect 5-10 stormwater samples | 13 |
| Mandurah (City of) | Estuary | MD3/411 | Eastern Foreshore | -32.530706, 115.71955 | 1. Program | 2013-2018 | 64 | 60 | B | 128 | 40 | Moderate | Good | Green | Collect 5-10 stormwater samples | 13 |
| Mandurah (City of) | Marina | MD3/310 | Marina Beach | -32.525389, 115.717531 | 1. Program | 2012-2018 | 78 | 3 | A | 28 | 15 | Low | Very Good | Green* | Annual SIR Review | 5 |
| Mandurah (City of) | Ocean | MD3/120 | Falcon Beach | -32.579771, 115.65221 | 1. Program | 2012-2018 | 78 | 18 | A | 57 | 21 | Low | Good (a) | Green* | Annual SIR Review | 5 |
| Mandurah (City of) | Ocean | MD3/155 | Halls Head Parade | -32.520261, 115.705116 | 1. Program | 2012-2018 | 78 | 80 | B | 199 | 45 | Low | Good | Green* | Annual SIR Review | 5 |
| Mandurah (City of) | Ocean | MD3/315 | Town Beach | -32.519516, 115.724056 | 1. Program | 2012-2018 | 78 | 20 | A | 64 | 18 | Low | Very Good | Green* | Annual SIR Review | 5 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|-------------------------|------------------------|----------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| Peel Region ... | | | | | | | | | | | | | | | | |
| Mandurah (City of) | Canal | MD3/280A | East Port | -32.607155, 115.646243 | 4. Active (Non-core) | 2013-2018 | 24 | 14 | A | 47 | 20 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Canal | MD3/280B | East Port | -32.601145, 115.650012 | 4. Active (Non-core) | 2013-2018 | 25 | 55 | B | 117 | 38 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Canal | MD3/375A | Mariners Cove | -32.554095, 115.733446 | 4. Active (Non-core) | 2013-2018 | 26 | 18 | A | 55 | 22 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Canal | MD3/375B | Mariners Cove | -32.550549, 115.732398 | 4. Active (Non-core) | 2014-2018 | 21 | 105 | B | 330 | 54 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Canal | MD3/401 | Aztec Island | -32.542958, 115.709397 | 4. Active (Non-core) | 2013-2018 | 26 | 3 | A | 26 | 14 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Canal | MD3/403 | Monterey Bay | -32.537982, 115.710208 | 4. Active (Non-core) | 2013-2018 | 26 | 30 | A | 140 | 10 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Canal | MD3/404 | Leslie Street Boat Ramp | -32.547972, 115.729858 | 4. Active (Non-core) | 2013-2018 | 27 | 85 | B | 387 | 40 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Estuary | MD3/200 | Mary Street Lagoon | -32.525418, 115.708011 | 4. Active (Non-core) | 2013-2018 | 32 | 2 | A | 17 | 12 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Estuary | MD3/400 | Southport | -32.605765, 115.636234 | 4. Active (Non-core) | 2013-2018 | 37 | 2 | A | 23 | 13 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Estuary | MD3/402 | Henry Sutton Grove | -32.530255, 115.71314 | 4. Active (Non-core) | 2013-2018 | 26 | 2 | A | 18 | 12 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Marina | MD3/206 | Mandurah Quay Marina | -32.559138, 115.70948 | 4. Active (Non-core) | 2013-2018 | 26 | 2 | A | 13 | 11 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Marina | MD3/405 | Mandurah Ocean Marina | -32.523946, 115.719782 | 4. Active (Non-core) | 2013-2018 | 26 | 6 | A | 34 | 15 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Ocean | MD3/095 | Tim`s Thicket | -32.653048, 115.61459 | 4. Active (Non-core) | 2013-2018 | 8 | 45 | B | 700 | 10 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Ocean | MD3/100 | Melrose Boat Ramp | -32.634396, 115.618829 | 4. Active (Non-core) | 2013-2018 | 8 | 3 | A | 26 | 14 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Ocean | MD3/105 | Pyramids Beach | -32.602718, 115.629067 | 4. Active (Non-core) | 2013-2018 | 28 | 36 | A | 140 | 10 | Not Avail | Not Avail | Green | | 5 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|---------------------------------|------------------------|------------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|--|-------------------------------|
| Peel Region ... | | | | | | | | | | | | | | | | |
| Mandurah (City of) | Ocean | MD3/110 | Westview Parade (Avalon) | -32.592582, 115.637482 | 4. Active (Non-core) | 2013-2018 | 28 | 30 | A | 140 | 10 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Ocean | MD3/150 | Blue Bay Leighton Road | -32.524469, 115.696717 | 4. Active (Non-core) | 2013-2018 | 26 | 5 | A | 140 | 10 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Ocean | MD3/165 | Orion Road | -32.50955, 115.732001 | 4. Active (Non-core) | 2013-2018 | 28 | 2 | A | 24 | 14 | Low | Very Good | Green | Annual SIR Review | 5 |
| Mandurah (City of) | Ocean | MD3/175 | Eros Place San Remo | -32.486346, 115.743062 | 4. Active (Non-core) | 2013-2018 | 28 | 8 | A | 37 | 14 | Low | Very Good | Green | Annual SIR Review | 5 |
| Mandurah (City of) | Ocean | MD3/180 | Madora Beach | -32.469157, 115.746114 | 4. Active (Non-core) | 2013-2018 | 28 | 2 | A | 17 | 10 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 5 |
| Mandurah (City of) | Ocean | MD3/135 | Gretel Road | -32.56693, 115.666368 | 5. Inactive (Non-core) | 2010-2013 | 17 | 16 | A | 140 | 10 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Ocean | MD3/145 | Janis Street | -32.529, 115.693566 | 5. Inactive (Non-core) | 2010-2013 | 17 | 38 | A | 140 | 29 | Not Avail | Not Avail | Green | | 5 |
| Mandurah (City of) | Canal | MD3/287 | North Port | | 6. Review | 2013-2018 | 20 | 80 | B | 700 | 22 | Not Avail | Not Avail | Green | | 5 |
| Murray (Shire of) | River | MY3/002 | Ravenswood Hotel - Murray River | -32.5855, 115.8268 | 1. Program | 2013-2018 | 63 | 105 | B | 145 | 56 | Moderate | Good | Green | Collect 5-10 upstream riverine & rainfall (24-48hrs) samples | 13 |
| Murray (Shire of) | River | MY3/003 | Murray River Bend | -32.597313, 115.833929 | 1. Program | 2013-2018 | 63 | 140 | B | 1793 | 74 | Moderate | Good | Green | Collect 5-10 upstream riverine & rainfall (24-48hrs) samples | 13 |
| Murray (Shire of) | River | MY3/005 | Pinjarra Boat Ramp | -32.624834, 115.874457 | 1. Program | 2013-2018 | 64 | 420 | C | 334 | 122 | Moderate | Poor | Red | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Murray (Shire of) | River | MY3/007 | Dwellingup Bridge | -32.7623, 116.0763 | 1. Program | 2013-2018 | 63 | 100 | B | 124 | 54 | Moderate | Good | Green | Collect 5-10 upstream riverine & rainfall (24-48hrs) samples | 13 |
| Murray (Shire of) | River | MY3/008 | Delta Drive | -32.5849, 115.7949 | 1. Program | 2013-2018 | 63 | 28 | A | 66 | 30 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|--------------------------------|------------------------|------------------------|---------------|-------------|-------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|--|-------------------------------|
| Peel Region ... | | | | | | | | | | | | | | | | |
| Murray (Shire of) | River | MY3/009 | Lucie Hunter Park | -32.585231, 115.779992 | 1. Program | 2013-2018 | 64 | 105 | B | 146 | 56 | Moderate | Good | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Murray (Shire of) | River | MY3/014 | Baden Powell (2) Steps | -32.771706, 116.084954 | 1. Program | 2013-2018 | 63 | 230 | C | 348 | 97 | Low | Follow up (b) | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Murray (Shire of) | River | MY3/020 | Tatham Rd Jetty | -32.577673, 115.810278 | 1. Program | 2013-2018 | 65 | 20 | A | 53 | 27 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Murray (Shire of) | Inlet | MY3/015 | Herron Point | | 3. Proposed | | | | | | | <i>Not Avail</i> | <i>Not Avail</i> | | Provide DoH SIR | 13 |
| Murray (Shire of) | River | MY3/006 | Coolup Bridge | -32.73503, 115.89988 | 3. Proposed | 2017-2018 | 12 | 2000 | D | 3824 | 716 | Moderate | Poor | Red | Collect 5-10 upstream riverine & rainfall (24-48hrs) samples | 13 |
| Murray (Shire of) | Inlet | MY3/018 | Coopers Mill | -32.575917, 115.765693 | 5. Inactive (Non-core) | 2012-2017 | 60 | 65 | B | 846 | 41 | Low | Good | Green | | 0 |
| Murray (Shire of) / DBCA | River | MY3/021 | Scarp Pool | -32.764576, 115.998208 | 5. Inactive (Non-core) | 2013-2018 | 64 | 75 | B | 120 | 46 | Low | Good | Green | | 0 |
| Waroona (Shire of) | Lake | WR3/001 | Drakesbrook Dam / Lake Moyanup | -32.858754, 115.951325 | 1. Program | 2013-2018 | 21 | 800 | D | 2720 | 396 | Moderate | Poor | Red | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Waroona (Shire of) / DBCA, DoT | Lake | WR3/002 | Waroona Dam / Lake Navarino | -32.851049, 115.990144 | 1. Program | 2012-2017 | 11 | 70 | B | 246 | 35 | Moderate | Good | Green | Collect 5-10 upstream riverine & rainfall (24-48hrs) samples | 13 |

DBCA = Department of Biodiversity, Conservation and Attractions
DoT = Department of Transport
DWER = Department of Water and Environmental Regulation



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|------------------------------------|------------------------|----------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|--|-------------------------------|
| South West Region | | | | | | | | | | | | | | | | |
| Augusta-Margaret River (Shire of) | Inlet | AM3/023 | Hardy Inlet - Turner Caravan Park | -34.32322, 115.16486 | 1. Program | 2013-2018 | 65 | 360 | C | 606 | 143 | Not Avail | Not Avail | Amber | Provide DoH SIR | 13 |
| Augusta-Margaret River (Shire of) | Ocean | AM3/012 | Gnarabup Beach (Jetty) | -33.99016, 114.9908 | 1. Program | 2012-2018 | 71 | 60 | B | 276 | 28 | Low | Good | Green* | Annual SIR Review | 5 |
| Augusta-Margaret River (Shire of) | Ocean | AM3/014 | Gracetown Beach | -33.86435, 114.98647 | 1. Program | 2012-2018 | 72 | 8 | A | 37 | 15 | Low | Very Good | Green* | Annual SIR Review | 5 |
| Augusta-Margaret River (Shire of) | Ocean | AM3/016 | Flinders Bay - Redman Brook | -34.34317, 115.16872 | 1. Program | 2013-2018 | 67 | 18 | A | 86 | 10 | Moderate | Good (a) | Green | Collect 5-10 rainfall (within 24-48hrs) & riverine samples | 13 |
| Augusta-Margaret River (Shire of) | River | AM3/001 | Margaret River - Canoe Landing | -33.96951, 114.988891 | 1. Program | 2012-2018 | 76 | 130 | B | 286 | 65 | Low | Good | Green* | Annual SIR Review | 5 |
| Augusta-Margaret River (Shire of) | River | AM3/002 | Margaret River - Rivermouth | -33.971092, 114.987313 | 1. Program | 2013-2018 | 54 | 130 | B | 202 | 63 | Moderate | Good | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Augusta-Margaret River (Shire of) | River | AM3/006 | Margaret River - Barrett St Weir | -33.94814, 115.08243 | 1. Program | 2013-2018 | 69 | 140 | B | 211 | 66 | High | Fair (a) | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Augusta-Margaret River (Shire of) | River | AM3/044 | Margaret River - Rendall Cl Weir | -33.949358, 115.086087 | 1. Program | 2013-2018 | 52 | 24 | A | 66 | 24 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Augusta-Margaret River (Shire of) | River | AM3/038 | Blackwood River - Alexandra Bridge | -34.164632, 115.183434 | 2. New | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Augusta-Margaret River (Shire of) | Drain | AM3/022 | Colour Patch Drain Foreshore | -34.324404, 115.167991 | 4. Active (Non-core) | 2013-2018 | 11 | 26 | A | 71 | 25 | Not Avail | Not Avail | Green | | 5 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|-------------------------------|-------------------------|----------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| South West Region ... | | | | | | | | | | | | | | | | |
| Bridgetown-Greenbushes (Shire of) | Pool | BS3/011 | Greenbushes Pool – Jetty West | -33.849547, 116.046296 | 3. Proposed | | | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Bridgetown-Greenbushes (Shire of) | Pool | BS3/012 | Greenbushes Pool – Jetty East | -33.849626, 116.046825 | 3. Proposed | | | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Bridgetown-Greenbushes (Shire of) | River | BS3/006 | Blackwood River - Bridge | -33.968129, 116.133683 | 3. Proposed | | | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Bridgetown-Greenbushes (Shire of) | River | BS3/010 | Blackwood River - Steps | -33.970747, 116.136272 | 3. Proposed | | | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Bunbury (City of) | Harbour | BC3/001 | Jetty Bath West | -33.31558, 115.63829 | 1. Program | 2013-2018 | 53 | 65 | B | 202 | 36 | Moderate | Good | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Bunbury (City of) | Ocean | BC3/012 | Koombana Beach | -33.31949, 115.64565 | 1. Program | 2013-2018 | 49 | 24 | A | 69 | 24 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Bunbury (City of) | Ocean | BC3/017 | Surf Club Beach | -33.32742, 115.62927 | 1. Program | 2012-2018 | 64 | 2 | A | 30 | 10 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 5 |
| Bunbury (City of) | Ocean | BC3/018 | Hungry Hollow | -33.33371, 115.62703 | 1. Program | 2013-2018 | 52 | 40 | A | 140 | 10 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Bunbury (City of) | Ocean | BC3/025 | Ski Beach | -33.319, 115.64005 | 1. Program | 2012-2018 | 64 | 22 | A | 68 | 19 | Moderate | Good (a) | Green | Collect 5-10 rainfall (within 24hrs) & Riverine samples | 5 |
| Bunbury (City of) | Drain | BC3/028 | Queens Gardens | -33.3260028, 115.641442 | 4. Active (Non-core) | 2016-2018 | 18 | 4600 | D | | 4981.07 | Not Avail | Not Avail | Red | | 5 |
| Bunbury (City of) | Estuary | BC3/002 | Estuary Plug | -33.320967, 115.641159 | 4. Active (Non-core) | 2016-2018 | 9 | 55 | B | 700 | 42 | Not Avail | Not Avail | Green | | 5 |
| Bunbury (City of) | Estuary | BC3/003 | Rowing Club | -33.324674, 115.64231 | 4. Active (Non-core) | 2016-2018 | 11 | 340 | C | 930 | 158 | Not Avail | Not Avail | Amber | | 5 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|-----------------------------------|------------------------|------------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| South West Region ... | | | | | | | | | | | | | | | | |
| Bunbury (City of) | Estuary | BC3/004 | Bunbury Yacht Club | -33.326464, 115.64709 | 4. Active (Non-core) | 2013-2018 | 8 | 210 | C | 730 | 106 | Not Avail | Not Avail | Amber | | 5 |
| Bunbury (City of) | Estuary | BC3/005 | Meredith Creek | -33.327144, 115.648331 | 4. Active (Non-core) | 2013-2018 | 19 | 115 | B | 395.64 | 57.3867 | Not Avail | Not Avail | Green | | 5 |
| Bunbury (City of) | Estuary | BC3/006 | Parade Hotel | -33.327536, 115.654558 | 4. Active (Non-core) | 2013-2018 | 17 | 75 | B | 178.104 | 42.6014 | Not Avail | Not Avail | Green | | 5 |
| Bunbury (City of) | Estuary | BC3/007 | Sofilas | -33.328099, 115.659039 | 4. Active (Non-core) | 2013-2018 | 17 | 175 | B | 821.89 | 91.9739 | Not Avail | Not Avail | Green | | 5 |
| Bunbury (City of) | Estuary | BC3/010 | Turkey Point | -33.306184, 115.674212 | 4. Active (Non-core) | 2013-2018 | 6 | | | | | Not Avail | Not Avail | | | 5 |
| Bunbury (City of) | Estuary | BC3/026 | Sykes Foreshore | -33.323328, 115.643394 | 4. Active (Non-core) | 2016-2018 | 18 | 145 | B | 351.918 | 71.107 | Not Avail | Not Avail | Green | Provide DoH SIR | 5 |
| Bunbury (City of) | Estuary | BC3/027 | Canoe Launch | -33.321661, 115.639896 | 4. Active (Non-core) | 2016-2018 | 19 | 210 | C | 508.494 | 100.095 | Not Avail | Not Avail | Amber | Provide DoH SIR | 5 |
| Bunbury (City of) | Harbour | BC3/021 | Harbour East | -33.31376, 115.640622 | 4. Active (Non-core) | 2013-2018 | 6 | | | | | Not Avail | Not Avail | | | 5 |
| Bunbury (City of) | Harbour | BC3/022 | Harbour West | -33.311596, 115.63806 | 4. Active (Non-core) | 2013-2018 | 6 | | | | | Not Avail | Not Avail | | | 5 |
| Bunbury (City of) | River | BC3/008 | Preston River | -33.326701, 115.671439 | 4. Active (Non-core) | 2013-2018 | 6 | | | | | Not Avail | Not Avail | | | 5 |
| Bunbury (City of) | River | BC3/009 | Collie River | -33.309425, 115.696352 | 4. Active (Non-core) | 2013-2018 | 6 | | | | | Not Avail | Not Avail | | | 5 |
| Bunbury (City of) | Drain | BC3/030 | Blair St Canal | -33.330719, 115.642928 | 5. Inactive (Non-core) | 2016 | 2 | | | | | Not Avail | Not Avail | | | 5 |
| Bunbury (City of) | Drain | BC3/023 | Meredith Creek Compensation Basin | -33.328163, 115.647122 | 6. Review | | | | | | | Not Avail | Not Avail | | | 5 |
| Bunbury (City of) | Drain | BC3/029 | Queens Pump | -33.325747, 115.641875 | 6. Review | | | | | | | Not Avail | Not Avail | | | 5 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|----------------------------------|------------------------|----------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| South West Region ... | | | | | | | | | | | | | | | | |
| Busselton (City of) | Ocean | BN3/023 | Margaret Street Beach (Site 8) | -33.650749, 115.324495 | 1. Program | 2013-2018 | 57 | 105 | B | 289 | 55 | Moderate | Good | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Busselton (City of) | Ocean | BN3/024 | Scout Beach (Site 6) | -33.655705, 115.234292 | 1. Program | 2013-2018 | 57 | 85 | B | 6912 | 16 | Moderate | Good | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Busselton (City of) | Ocean | BN3/025 | Forth Street Beach (Site 7) | -33.656216, 115.248267 | 1. Program | 2013-2018 | 56 | 95 | B | 450 | 47 | Moderate | Good | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Busselton (City of) | Ocean | BN3/028 | Busselton Jetty Ocean 9 | -33.644157, 115.344108 | 1. Program | 2013-2018 | 56 | 470 | C | 48940 | 858 | Moderate | Poor | Red | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Busselton (City of) | Creek | BN3/022 | Margaret St - Creek | -33.651729, 115.32365 | 4. Active (Non-core) | 2014-2018 | 37 | 980 | D | 898 | 254 | Not Avail | Not Avail | Red | | 5 |
| Busselton (City of) | Creek | BN3/027 | Forth St - Creek | -33.65705, 115.24761 | 4. Active (Non-core) | 2014-2018 | 36 | 130 | B | 283 | 66 | Not Avail | Not Avail | Green | | 5 |
| Busselton (City of) / DWER | Creek | BN3/043 | Wonnerup Floodgate | -33.619346, 115.41385 | 4. Active (Non-core) | 2015-2018 | 40 | 34 | A | 77 | 30 | Not Avail | Not Avail | Green | | 5 |
| Busselton (City of) / DWER | Creek | BN3/044 | Wonnerup Inlet Road Bridge | -33.61663, 115.420272 | 4. Active (Non-core) | 2015-2018 | 41 | 780 | D | 3515 | 439 | Not Avail | Not Avail | Red | | 5 |
| Busselton (City of) | Drain | BN3/021 | Margaret St - Drain | -33.65324, 115.32367 | 4. Active (Non-core) | 2014-2018 | 37 | 680 | D | 81803 | 1638 | Not Avail | Not Avail | Red | | 5 |
| Busselton (City of) | Marina | BN3/355 | Port Geographe - Swimming Lagoon | -33.629892, 115.389677 | 4. Active (Non-core) | 2015-2018 | 29 | 12 | A | 140 | 10 | Not Avail | Not Avail | Green | | 5 |
| Busselton (City of) / DWER | Ocean | BN3/045 | Wonnerup Inlet Ocean Mouth | -33.610202, 115.423175 | 4. Active (Non-core) | 2015-2018 | 26 | 40 | A | 84 | 35 | Not Avail | Not Avail | Green | | 5 |
| Capel (Shire of) | Ocean | CP3/001 | Forrest Beach | -33.57244, 115.46048 | 1. Program | 2013-2018 | 30 | 740 | D | 4548 | 483 | Moderate | Poor | Red | Collect 5-10 rainfall (24-48 hrs) samples | 13 |
| Capel (Shire of) | Ocean | CP3/002 | Peppermint Grove Beach | -33.527373, 115.504204 | 1. Program | 2013-2018 | 30 | 60 | B | 252 | 26 | Moderate | Good | Green | Collect 5-10 rainfall (24-48 hrs) samples | 13 |
| Capel (Shire of) | Ocean | CP3/003 | Minninup Beach | -33.451544, 115.575228 | 1. Program | 2013-2018 | 30 | 250 | C | 1453 | 143 | Moderate | Poor | Red | Collect 5-10 rainfall (24-48 hrs) samples | 13 |



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|--|------------------------|----------------------|---------------|-------------|-------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| South West Region ... | | | | | | | | | | | | | | | | |
| Capel (Shire of) | Ocean | CP3/004 | Dalyellup Beach | -33.404978, 115.600615 | 1. Program | 2013-2018 | 29 | 80 | B | 397 | 37 | Moderate | Good | Green | Collect 5-10 rainfall (24-48 hrs) samples | 13 |
| Capel (Shire of) | River | CP3/005 | Preston River - Boyanup | -33.478692, 115.733701 | 1. Program | 2012-2018 | 38 | 2100 | D | 1257 | 385 | High | Very Poor | Red* | Recommend permanent warning sign | 5 |
| Capel (Shire of) | River | CP3/006 | Capel River - Mallokup Bridge | -33.519698, 115.537251 | 1. Program | 2013-2018 | 30 | 90 | B | 142 | 50 | High | Poor | Red | Collect 5-10 rainfall, upstream Riverine + regular site samples | 13 |
| Capel (Shire of) | Ocean | CP3/008 | North Dalyellup Beach | -33.397131, 115.603824 | 2. New | 2013-2018 | 8 | 14 | A | 140 | 10 | <i>Not Avail</i> | <i>Not Avail</i> | Green | Provide DoH SIR | 13 |
| Capel (Shire of) | Ocean | CP3/007 | Water Corp Dalyellup Beach | -33.382122, 115.609281 | 4. Active (Non-core) | 2015-2017 | 6 | | | | | <i>Not Avail</i> | <i>Not Avail</i> | | | 5 |
| Collie (Shire of) / Dept. of Planning, Lands & Heritage | Lake | CI3/003 | Black Diamond Recreational Water Area | -33.34257, 116.092729 | 1. Program | 2015-2018 | 31 | 2 | A | 14 | 11 | Low | Very Good | Green | Annual SIR Review | 13 |
| Collie (Shire of)/ DBCA | Lake | CI3/004 | Stockton Lake | -33.384219, 116.228083 | 1. Program | 2016-2018 | 20 | | A | | 10 | Low | Very Good | Green | Annual SIR Review | 13 |
| Collie (Shire of) / DBCA | Reservoir | CI3/001 | Potters Gorge - Wellington Dam | -33.390301, 115.983908 | 1. Program | 2015-2017 | 4 | | | | | Low | <i>Not Avail</i> | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Collie (Shire of) / DBCA | River | CI3/002 | Honeymoon Pool - Preston River | -33.379581, 115.938206 | 1. Program | 2015-2017 | 10 | 30 | A | 63 | 32 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Collie (Shire of) | River | CI3/005 | Minninup Pool - Front Parking Area | -33.376853, 116.138084 | 1. Program | 2016-2018 | 18 | 2000 | D | 6668 | 982 | Moderate | Poor | Red | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Collie (Shire of) / DBCA | Lake | CI3/008 | Lake Kepwari Beach | -33.457582, 116.232609 | 2. New | | | | | | | Moderate | <i>Not Avail</i> | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Collie (Shire of) / DBCA | Lake | CI3/010 | Lake Kepwari North Outlet | -33.456461, 116.23143 | 2. New | | | | | | | Moderate | <i>Not Avail</i> | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Collie (Shire of) / DBCA | Lake | CI3/009 | Lake Kepwari Boat Ramp | -33.459739, 116.233246 | 3. Proposed | | | | | | | Moderate | <i>Not Avail</i> | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Collie (Shire of) / Dept. of Planning, Lands & Heritage | Lake | CI3/011 | Black Diamond Lake - Side Parking Area | -33.342633, 116.091694 | 3. Proposed | | | | | | | Low | <i>Not Avail</i> | Green | Annual SIR Review | 13 |

DBCA = Department of Biodiversity, Conservation and Attractions
DoT = Department of Transport
DWER = Department of Water and Environmental Regulation



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|---|------------------------|----------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| South West Region ... | | | | | | | | | | | | | | | | |
| Collie (Shire of) | River | CI3/006 | Minninup Pool - Stone Stairwell | -33.377038, 116.137753 | 4. Active (Non-core) | 2016-2018 | 13 | 220 | C | 462 | 100 | Moderate | Poor | Red | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Collie (Shire of) | River | CI3/007 | Minninup Pool - Side Parking Area | -33.377727, 116.139517 | 4. Active (Non-core) | 2016-2018 | 10 | 115 | B | 194 | 58 | Moderate | Good | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Donnybrook-Balingup (Shire of) / DBCA, DoT | Reservoir | DB3/015 | Glen Mervyn Dam - NE | -33.49363, 116.101592 | 3. Proposed | | | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48 hrs) samples | 13 |
| Donnybrook-Balingup (Shire of) / DBCA, DoT | Reservoir | DB3/016 | Glen Mervyn Dam - Campsite SW | -33.498608, 116.097755 | 3. Proposed | | | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48 hrs) samples | 13 |
| Donnybrook-Balingup (Shire of) | River | DB3/013 | Preston River - Donnybrook Amphitheatre | -33.575903, 115.826496 | 4. Active (Non-core) | 2014-2018 | 10 | 260 | C | 211 | 87 | Moderate | Poor | Red | | 5 |
| Donnybrook-Balingup (Shire of) | River | DB3/014 | Preston River - Footbridge | -33.57437, 115.825772 | 4. Active (Non-core) | 2014 | 1 | | | | | Moderate | Not Avail | Amber | | 5 |
| Harvey (Shire of)/ DBCA | Lake | HA3/027 | Lake Brockman Boat Ramp | -33.002994, 115.971344 | 1. Program | 2014-2018 | 31 | 34 | A | 96 | 25 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) & riverine samples | 13 |
| Harvey (Shire of) | Ocean | HA3/020 | Myalup Beach | -33.103452, 115.686984 | 1. Program | 2013-2018 | 37 | 2 | A | 17 | 11 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Harvey (Shire of) | Ocean | HA3/021 | Binningup Beach | -33.148933, 115.685686 | 1. Program | 2013-2018 | 37 | 75 | B | 700 | 10 | Moderate | Good (a) | Green | Collect 5-10 rainfall (within 24hrs) samples | 13 |
| Harvey (Shire of) | Reservoir | HA3/026 | Harvey Dam Boat Ramp | -33.081085, 115.953328 | 1. Program | 2014-2018 | 31 | 60 | B | 249 | 29 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48hrs) samples | 13 |

DBCA = Department of Biodiversity, Conservation and Attractions
DoT = Department of Transport
DWER = Department of Water and Environmental Regulation



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|--|------------------------|---------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|--|-------------------------------|
| South West Region ... | | | | | | | | | | | | | | | | |
| Manjimup (Shire of) | Inlet | MJ3/010 | Walpole Inlet - Jones St Jetty | -34.97782, 116.7247 | 3. Proposed | 2017-2018 | 3 | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Manjimup (Shire of) / DBCA | Inlet | MJ3/014 | Nornalup Inlet - Sandy Beach | -34.99576, 116.71322 | 3. Proposed | 2017-2018 | 3 | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Manjimup (Shire of) | Inlet | MJ3/015 | Nornalup Inlet - Coalmine Beach | -34.99012, 116.73653 | 3. Proposed | 2017-2018 | 3 | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Manjimup (Shire of) | Pool | MJ3/020 | Pemberton Pool | -34.44303, 116.02999 | 3. Proposed | 2017-2018 | 3 | | | | | Moderate | Not Avail | Amber | Collect 5-10 upstream riverine & rainfall (24-48hrs) samples | 13 |
| Manjimup (Shire of) / DBCA | Reservoir | MJ3/021 | Big Brook Dam | -34.40591, 116.02678 | 3. Proposed | 2017-2018 | 3 | | | | | Low | Not Avail | Green | Annual SIR Review | 13 |
| Manjimup (Shire of) / Private | Reservoir | MJ3/022 | Karri Valley Resort | -34.42122, 115.86158 | 3. Proposed | 2017-2018 | 3 | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Manjimup (Shire of) / Private | Reservoir | MJ3/1811 | Fonty's Pool - SE Cnr Pool (near outlet) | -34.28951, 116.06519 | 3. Proposed | 2017-2018 | 2 | | | | | Moderate | Not Avail | Amber | Collect 5-10 upstream riverine & rainfall (24-48hrs) samples | 13 |
| Manjimup (Shire of) | River | MJ3/023 | Pemberton Pool South East Corner | -34.44344, 116.02970 | 3. Proposed | 2017-2018 | 2 | | | | | Moderate | Not Avail | Amber | Collect 5-10 upstream riverine & rainfall (24-48hrs) samples | 13 |
| Nannup (Shire of) / DBCA | River | NA3/001 | Barrabup Pool - Platform | -33.944341, 115.691157 | 2. New | 2016-2018 | 4 | | | | | Moderate | Not Avail | Amber | Collect 5-10 upstream riverine & rainfall (24-48hrs) samples | 13 |
| Nannup (Shire of) / DBCA | River | NA3/002 | Workers Pool - Steps | -33.953875, 115.686802 | 2. New | 2016-2018 | 4 | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Nannup (Shire of) | Reservoir | NA3/004 | Donnelly River Village Dam | -34.099146, 115.980946 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Nannup (Shire of) | River | NA3/006 | Nannup Townsite Bridge | -33.974655, 115.761673 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |

DBCA = Department of Biodiversity, Conservation and Attractions
DoT = Department of Transport
DWER = Department of Water and Environmental Regulation



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|----------------------------------|------------------------|---------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| Wheatbelt Region | | | | | | | | | | | | | | | | |
| Dandaragan (Shire of) / DoT | Harbour | DA3/006 | Jurien Boat Harbour Beach (West) | -30.291149, 115.044075 | 1. Program | 2013-2018 | 28 | 40 | A | 109 | 29 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48 hrs) samples | 13 |
| Dandaragan (Shire of) / DoT | Harbour | DA3/007 | Jurien Boat Harbour Beach (East) | -30.290526, 115.045607 | 1. Program | 2013-2018 | 29 | 18 | A | 58 | 20 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48 hrs) samples | 13 |
| Dandaragan (Shire of) | Ocean | DA3/013 | Dobbyn Park Beach | -30.301367, 115.03697 | 1. Program | 2013-2018 | 33 | 2 | A | 14 | 11 | Moderate | Good (a) | Green | Collect 5-10 rainfall (24-48 hrs) samples | 13 |
| Dandaragan (Shire of) | Ocean | DA3/015 | Cervantes - Swimming Beach | -30.495617, 115.065755 | 1. Program | 2013-2018 | 34 | 240 | C | 22448 | 245 | Moderate | Poor | Red | Annual SIR Review | 13 |
| Dandaragan (Shire of) | Ocean | DA3/016 | Cervantes - Jetty/Boat Ramp | -30.491262, 115.068565 | 1. Program | 2013-2018 | 34 | 2 | A | 19 | 13 | Moderate | Good (a) | Green | Annual SIR Review | 13 |
| Gingin (Shire of) | River | GG3/001 | Moore River - Mouth Beach | -31.352224, 115.499251 | 1. Program | 2013-2018 | 28 | 22 | A | 60 | 25 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Gingin (Shire of) | River | GG3/002 | Moore River - Caravan Park | -31.351037, 115.500438 | 1. Program | 2013-2018 | 28 | 165 | B | 305 | 77 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Gingin (Shire of) | River | GG3/003 | Moore River - Boat Ramp | -31.351811, 115.502752 | 1. Program | 2013-2018 | 28 | 170 | B | 547 | 84 | Not Avail | Not Avail | Green | Provide DoH SIR | 13 |
| Gingin (Shire of) | River | GG3/010 | Moore River Desert Boardwalk | -31.01071, 115.3279 | 1. Program | 2013-2018 | 28 | 210 | C | 341 | 91 | Not Avail | Not Avail | Amber | Provide DoH SIR | 13 |
| Gingin (Shire of) / DBCA | Ocean | GG3/011 | Grace Darling Park Bch | -31.0246, 115.3282 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Gingin (Shire of) / DBCA | Ocean | GG3/012 | Harold Park Bch | -31.010732, 115.327557 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |

DBCA = Department of Biodiversity, Conservation and Attractions
DoT = Department of Transport
DWER = Department of Water and Environmental Regulation



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

| Local Government Authority (LGA)/ Managing Authority (MA) | Water Body | Site Code | Site Name | GPS Deci-degrees | Monitoring Category | Results Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category | Provisional Class | Provisional Colour | LGA/ MA Sanitary Inspection Report (SIR) Status Actions | Min No. Samples Rqd 2018-2019 |
|---|------------|-----------|---|------------------------|---------------------|---------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------|-------------------|--------------------|---|-------------------------------|
| Wheatbelt Region | | | | | | | | | | | | | | | | |
| Narrogin (Shire of) | Reservoir | NG3/001 | Railway Dam - South | -32.947662, 117.178997 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| Narrogin (Shire of) | Reservoir | NG3/002 | Railway Dam - North | -32.947225, 117.179656 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |
| West Arthur (Shire of) / DBCA, DoT | Lake | AW3/001 | Lake Towerrinning - Jetty 1 | -33.583888, 116.791518 | 1. Program | 2013-2018 | 34 | 700 | D | 2526 | 357 | Moderate | Poor | Red | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| West Arthur (Shire of) / DBCA, DoT | Lake | AW3/002 | Lake Towerrinning - Caravan Park | -33.588671, 116.78572 | 1. Program | 2013-2018 | 30 | 740 | D | 2110 | 338 | Not Avail | Not Avail | Red | Provide DoH SIR | 13 |
| Wickepin (Shire of) | Lake | WI3/001 | Yealering Lake Swimming Hole - NE Corner | -32.596442, 117.634081 | 3. Proposed | | | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| Wickepin (Shire of) | Lake | WI3/006 | Yealering Lake Swimming Hole - End of Jetty | -32.595164, 117.627225 | 3. Proposed | | | | | | | Moderate | Not Avail | Amber | Collect 5-10 rainfall (24-48hrs) samples | 13 |
| York (Shire of) | Reservoir | YO3/007 | WhiteGum Farm Dam | -31.866532, 116.939709 | 3. Proposed | | | | | | | Not Avail | Not Avail | | Provide DoH SIR | 13 |

DBCA = Department of Biodiversity, Conservation and Attractions
DoT = Department of Transport
DWER = Department of Water and Environmental Regulation