



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2015 - Garden Island

| LGA/ Managing Authority            | Water Body | Site Code | Site Name      | Result Years | No. Samples | 95th %tile | Microbial Assess Category (MAC) | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assess Category (SAC) | Provisional Class | Provisional Colour | SAC Status Actions                         | Min No. Samples Rqd 2015-2016 |
|------------------------------------|------------|-----------|----------------|--------------|-------------|------------|---------------------------------|----------------------------------|---------------------------------------|--------------------------------|-------------------|--------------------|--|-------------------------------|
| Commonwealth Department of Defence | Ocean      | EV3/741   | Cliff Head     | 2008-2014    | 13          | 18         | A                               | 140                              | 10                                    | Moderate - F/U                 | Good (a)          | Green              | Collect 10 rainfall (within 24hrs) samples | 13                            |
| Commonwealth Department of Defence | Ocean      | EV3/742   | Pig Trough Bay | 2008-2014    | 13          | 2          | A                               | 140                              | 12                                    | Moderate - F/U                 | Good (a)          | Green              | Collect 10 rainfall (within 24hrs) samples | 13                            |
| Commonwealth Department of Defence | Ocean      | EV3/743   | Herring Cove   | 2008-2014    | 12          | 20         | A                               | 140                              | 10                                    | Moderate - F/U                 | Good (a)          | Green              | Collect 10 rainfall (within 24hrs) samples | 13                            |
| Commonwealth Department of Defence | Ocean      | EV3/769   | Camp Markham   |              |             |            |                                 |                                  |                                       | Assessment Required            | Not Avail         |                    | Provide DoH Sanitary Inspection Report     | 13                            |