

Recreational Waters Metropolitan Oceans Bacterial Monitoring Program - Site Status Overview: 2006 - 2012

Site Code	LGA	Site Name	Result Years	No. samples	95th %tile	MAC	1 sample Trigger Level 99th %tile	2 samples in-a-row Trigger Level 90th %tile	SAC	SIC Factor	SIC Status Comments	Provisional Classification	Provisional Web Colour	Min No. LGA samples Rqd 2012-2013
EV3/739	Wanneroo	Quinns Rock	2007-2012	70	28	A	327	10	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/759	Wanneroo	Mindarie (Claytons Beach)	2007-2012	69	6	A	37	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
EV3/762	Wanneroo	Yanchep Lagoon	2009-2012	64	26	A	237	10	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/763	Wanneroo	Two Rocks - Leemans Landing	2009-2012	63	26	A	14741	10	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/764	Wanneroo	Two Rocks (Sovereign Park)	2009-2012	64	2	A	20	10	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	5
EV3/720	Stirling	Scarborough Beach	2007-2012	85	6	A	33	10	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
EV3/721	Stirling	Trigg Island	2007-2012	82	3	A	27	15	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
EV3/722	Stirling	Mettams Pool	2007-2012	68	38	A	553	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/723	Stirling	Hammersley Pool	2007-2012	81	8	A	45	10	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	12
EV3/724	Stirling	Watermans Beach	2007-2012	75	2	A	31	10	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
EV3/755	Stirling	Scarborough Beach North	2007-2012	79	9	A	10	10	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
EV3/756	Stirling	Scarborough Beach South	2007-2012	68	32	A	146	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/757	Stirling	South Trigg Beach	2007-2012	68	2	A	18	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
EV3/701	Rockingham	Rockingham Beach	2007-2012	83	38	A	97	28	Low	Rainfall	Awaiting stormwater drain monitoring results	Very Good	Green	12
EV3/750	Rockingham	Palm Beach (Next to Jetty)	2007-2012	82	14	A	47	18	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/760	Rockingham	North Hymus	2007-2012	70	22	A	66	22	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
RK3/012	Rockingham	Waikiki Beach	2008-2012	63	45	B	157	23	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
RK3/027	Rockingham	Secret Harbour Surf Club	2009-2012	42	16	A	51	20	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12

Recreational Waters Metropolitan Oceans Bacterial Monitoring Program - Site Status Overview: 2006 - 2012

Site Code	LGA	Site Name	Result Years	No. samples	95th %tile	MAC	1 sample Trigger Level 99th %tile	2 samples in-a-row Trigger Level 90th %tile	SAC	SIC Factor	SIC Status Comments	Provisional Classification	Provisional Web Colour	Min No. LGA samples Rqd 2012-2013
EV3/717	Nedlands	Swanbourne Beach	2007-2012	69	34	A	102	22	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	12
EV3/706	Kwinana	Naval Base	2007-2012	70	30	A	118	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/751	Kwinana	Kwinana Beach	2007-2012	70	9	A	39	15	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
EV3/725	Joondalup	Hillarys South Break	2007-2012	69	14	A	51	16	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/728	Joondalup	Hillarys South Swim	2007-2012	69	70	B	144	43	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
EV3/729	Joondalup	Hillarys Middle Swim	2007-2012	69	38	A	87	31	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/730	Joondalup	Hillarys North Swim	2007-2012	70	28	A	73	26	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/731	Joondalup	Pinaroo Point	2007-2012	71	115	B	339	59	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
EV3/732	Joondalup	Mullaloo Beach	2007-2012	70	6	A	33	15	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
EV3/733	Joondalup	Korella Street	2007-2012	70	16	A	70	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/736	Joondalup	Burns Beach	2007-2012	69	34	A	120	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/758	Joondalup	Sorrento Beach (Surf Club)	2007-2012	65	7	A	36	10	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
EV3/711	Fremantle	South Beach	2007-2012	69	32	A	79	28	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/713	Fremantle	Fremantle Swimmers Beach	2007-2012	65	14	A	49	17	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/714	Fremantle	Port Beach	2007-2012	81	2	A	28	10	Moderate	Rainfall	Collect 5 rainfall samples	Good (a)	Green	5
EV3/715	Fremantle	Leighton Beach	2007-2012	66	24	A	202	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	12
EV3/716	Cottesloe	Cottesloe Beach	2007-2012	62	28	A	77	26	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	5
EV3/753	Cottesloe	Cottesloe North	2007-2012	61	36	A	191	10	Outstanding		Provide DoH Sanitary Inspection Report	Not Available	Green	5

Recreational Waters Metropolitan Oceans Bacterial Monitoring Program - Site Status Overview: 2006 - 2012

Site Code	LGA	Site Name	Result Years	No. samples	95th %tile	MAC	1 sample Trigger Level 99th %tile	2 samples in-a-row Trigger Level 90th %tile	SAC	SIC Factor	SIC Status Comments	Provisional Classification	Provisional Web Colour	Min No. LGA samples Rqd 2012-2013
CK3/997	Cockburn	Port Coogee	2011-2012	22	90	B	181	49	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	12
EV3/709	Cockburn	Coogee Beach	2007-2012	65	5	A	31	15	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
EV3/710	Cockburn	C.Y.O'Connor Beach	2007-2012	67	95	B	309	48	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	12
EV3/752	Cockburn	Jervoise Bay Beach	2007-2012	65	22	A	67	19	Moderate	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	12
EV3/718	Cambridge	City Beach	2007-2012	67	3	A	28	15	Low	Rainfall	Collect 5 rainfall (within 24hrs) samples	Very Good	Green	5
EV3/719	Cambridge	Floreat Beach	2007-2012	53	8	A	140	10	Low	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Very Good	Green	12
EV3/754	Cambridge	City Beach North	2007-2012	54	34	A	140	20	Low	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Very Good	Green	12