



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
<b>Gascoyne Region</b>																
Shire of Carnarvon	Inlet	CN3/001	Carnarvon Town Beach	-24.898049, 113.640697	Program	2011-2015	45	90	B	334	45	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/003	Facsine Beach	-24.883493, 113.65417	Program	2011-2015	48	40	A	94	33	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/004	Before Yacht Club	-24.89152, 113.654091	Program	2011-2015	48	45	B	700	20	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/005	Yacht Club	-24.89233, 113.654028	Program	2013-2015	33	30	A	140	12	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/045	Fascine Jetty	-24.884065, 113.653027	Program	2011-2015	48	18	A	52	25	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Ocean	CN3/046	Pelican Point Beach	-24.897549, 113.638457	Program	2011-2015	35	6	A	33	16	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Harbour	CN3/043	Boat Harbour Snapper Jetty	-24.898193, 113.65109	Reference	2011-2015	44	6	A	36	19	Not Avail	Not Avail	Green		5
Shire of Carnarvon	Harbour	CN3/044	Boat Harbour Wharf	-24.899092, 113.650946	Reference	2011-2015	44	5	A	32	19	Not Avail	Not Avail	Green		5
Shire of Carnarvon	Inlet	CN3/006	Yacht Club Marina	-24.894711, 113.653688	Reference	2013-2015	33	16	A	48	25	Not Avail	Not Avail	Green		5
Shire of Carnarvon	Inlet	CN3/041	Northwater DB Drive	-24.881972, 113.65414	Reference	2011-2015	37	60	B	137	37	Not Avail	Not Avail	Green		5
Shire of Carnarvon	Inlet	CN3/042	Northwater Jaaga	-24.88268, 113.649727	Reference	2012-2015	39	80	B	370	39	Not Avail	Not Avail	Green		5
Shire of Carnarvon	River	CN3/047	Chinamans Pool	-24.860979, 113.673522	Reference	2011-2015	32	720	D	1329	271	Not Avail	Not Avail	Red		5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018	
<b>Gascoyne Region ...</b>																	
Shire of Exmouth	Canal	EX3/057	Canal Nr Bridge Horwood Side	-21.954736, 114.135727	Program	2012-2017	41	9	A	39	18	Moderate	Good (a)	Green	Collect 5-10 storm-water drain samples	13	
Shire of Exmouth/ DoT	Harbour	EX3/050	Small Boat Harbour - Boat Ramp	-21.955913, 114.13953	Program	2012-2017	31	2	A	19	14	Low	Very Good	Green	Annual Review	13	
Shire of Exmouth	Ocean	EX3/051	Exmouth Town Beach	-21.945644, 114.140116	Program	2012-2017	34	50	B	118	35	Low	Good	Green	Annual Review	13	
<b>Goldfields - Esperance Region</b>																	
Shire of Esperance/ DoT	Harbour	ES3/030	Bandy Creek Harbour	-33.831938, 121.933446	Program	2012-2017	55	280	C	1750	160	Moderate	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13	
Shire of Esperance	Ocean	ES3/031	James St Groyne	-33.860941, 121.89603	Program	2012-2017	54	130	B	271	65	Moderate	Good	Green	Collect 5-10 storm-water drain samples	13	
Shire of Esperance/ Southern Port Authority	Ocean	ES3/032	Port Authority Beach	-33.867722, 121.895011	Program	2012-2017	53	105	B	230	55	Moderate	Good	Green	Collect 5-10 storm-water drain samples	13	
<b>Great Southern Region</b>																	
City of Albany	Harbour	AC3/009	Boatshed Beach - Princess Royal Harbour	-35.031225, 117.889195	Proposed	Not Available										Provide DOH Sanitary Inspection Report	13
City of Albany	Inlet	AC3/007	Emu Beach - Oyster Harbour	-34.996985, 117.947777	Proposed	2014-2015	8	2200	D		145	Not Avail	Not Avail	Red	Provide DOH Sanitary Inspection Report	13	
City of Albany	Ocean	AC3/008	Ellen Cove (Jetty) - Middleton Beach	-35.025484, 117.918298	Proposed	Not Available										Provide DOH Sanitary Inspection Report	13
City of Albany	Ocean	AC3/010	Frenchman Bay	-35.092244, 117.94883	Proposed	Not Available										Provide DOH Sanitary Inspection Report	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
<b>Great Southern Region ...</b>																
Shire of Denmark	Creek	DK3/024	Peaceful Bay - Creek/Drain	-35.041636, 116.929175	Point Source	2012-2017	38	490	C	891	191	N/A	Not Avail	Amber	N/A	5
Shire of Denmark	Drain	DK3/023	Peaceful Bay Open Drain - Foot Bridge	-35.041127, 116.928611	Point Source	2012-2017	37	740	D	748	211	N/A	Not Avail	Red	N/A	5
Shire of Denmark	Drain	DK3/042	Nornalup - Drain Outlet	-34.990902, 116.815937	Point Source	2012-2017	37	380	C	791	160	N/A	Not Avail	Amber	N/A	5
Shire of Denmark	Reservoir	DK3/022	Peaceful Bay - Water Supply Dam	-35.040871, 116.927578	Point Source	2012-2017	39	900	D	1983	361	N/A	Not Avail	Red	N/A	5
Shire of Denmark	Inlet	DK3/050	Wilson Inlet - Ocean Beach Caravan Park	-35.02107, 117.327082	Program	2012-2013	26	45	B	700	10	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Inlet	DK3/051	Wilson Inlet - Yacht Club Gazebo	-34.975896, 117.366096	Program	2012-2017	30	185	B	1039	100	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Ocean	DK3/025	Peaceful Bay - Ocean	-35.041714, 116.92976	Reference	2012-2017	39	55	B	188	27	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Ocean	DK3/025A	Peaceful Bay - Ocean (South)	-35.042113, 116.929721	Reference	2012-2017	39	7	A	35	13	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Ocean	DK3/025B	Peaceful Bay - Ocean (North)	-35.041352, 116.929873	Reference	2012-2017	39	30	A	106	16	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Inlet	DK3/053	Wilson Inlet - Rivermouth Caravan Park	-34.970279, 117.369053	Review	2012-2017	30	500	C	1482	237	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Inlet	DK3/055	Wilson Inlet - Springdale Beach 6	-34.969435, 117.387766	Review	2012-2013	25	100	B	333	52	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	River	DK3/054	Denmark River - Berridge Park	-34.959994, 117.357211	Review	2011-2017	43	1100	D	2051	401	Not Avail	Not Avail	Red	Provide DOH Sanitary Inspection Report	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
<b>Kimberley Region</b>																
Shire of Broome	Ocean	BM3/070	Gantheaume Point	-17.972379, 122.187052	Proposed										Provide DOH Sanitary Inspection Report	13
Shire of Broome	Ocean	BM3/071	Cable Beach	-17.931514, 122.209044	Proposed										Provide DOH Sanitary Inspection Report	13
Shire of Broome/ Broome Port Authority	Ocean	BM3/072	Port Authority Beach	-18.001231, 122.209594	Proposed										Provide DOH Sanitary Inspection Report	13
Shire of Broome	Ocean	BM3/073	Town Beach Roebuck Bay	-17.971442, 122.235969	Proposed										Provide DOH Sanitary Inspection Report	13
Shire of Halls Creek	Lake	HC3/002	Lake Komaterpila	-18.346907, 127.823112	Proposed										Provide DOH Sanitary Inspection Report	13
Shire of Halls Creek	Pool	HC3/001	Caroline Pool	-18.226293, 127.758536	Proposed										Provide DOH Sanitary Inspection Report	13
Shire of Halls Creek	River	HC3/003	Palm Springs	-18.420166, 127.845376	Proposed										Provide DOH Sanitary Inspection Report	13
Shire of Halls Creek	Stream	HC3/004	Sawpit Gorge	-18.424952, 127.820059	Proposed										Provide DOH Sanitary Inspection Report	13
<b>Midwest Region</b>																
City of Greater Geraldton	Ocean	GE3/001	Town Beach Jetty	-28.772771, 114.60733	Program	2012-2017	36	2	A	12	11	High	Good (a)	Green	Collect 5-10 storm- water drain samples	13
City of Greater Geraldton	Ocean	GE3/003	Point Moore North	-28.782423, 114.577166	Program	2012-2017	34	45	B	115	29	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/005	Separation Point	-28.78948, 114.59664	Program	2011-2014	27	70	B	126	43	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/006	Back Beach	-28.79514, 114.611337	Program	2012-2017	35	28	A	140	10	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/008	Marina North	-28.763243, 114.614429	Program	2012-2017	34	2	A	25	16	Moderate	Good (a)	Green	Collect 5-10 storm- water drain samples	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
<b>Midwest Region ...</b>																
City of Greater Geraldton	Ocean	GE3/010	Saint Georges	-28.745934, 114.617895	Program	2012-2017	36	24	A	140	20	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/012	Sunset Beach - Triton Place	-28.721125, 114.6192	Program	2012-2017	31	55	B	164	32	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
City of Greater Geraldton	Ocean	GE3/021	Pages Beach North	-28.776499, 114.583602	Program	2012-2017	37	185	B	409	87	Moderate	Good	Green	Collect 5-10 storm-water drain samples	13
City of Greater Geraldton	Ocean	GE3/022	Tarcoola Beach	-28.81802, 114.62311	Program	2012-2017	33	38	A	125	22	Very Low	Very Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/023	Greenough Beach	-28.861882, 114.63482	Program	2012-2017	33	22	A	140	13	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/026	Drummonds Cove	-28.670796, 114.611879	Program	2011-2014	23	45	B	106	32	Low	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	River	GE3/024	Greenough River Mouth	-28.862921, 114.638199	Program	2012-2017	36	190	B	700	262	High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
City of Greater Geraldton	River	GE3/025	Ellendale Pool	-28.860916, 114.973733	Program	2011-2017	47	320	C	434	119	High	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Irwin	Harbour	IR3/080	Marina (Boat Ramp)	-29.274863, 114.91862	Program	2011-2017	27	30	A	140	10	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Irwin	Ocean	IR3/001	Nun's Pool	-29.261797, 114.920922	Program	2011-2017	27	75	B	700	10	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
Shire of Irwin	Ocean	IR3/060	South Beach	-29.283478, 114.919042	Program	2011-2017	27	14	A	49	18	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Irwin	Ocean	IR3/070	Granny's Beach	-29.271023, 114.92187	Program	2011-2017	27	18	A	60	18	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
<b>Peel Region</b>																
City of Mandurah	Canal	MD3/330	Hall Park	-32.533631, 115.716415	Program	2012-2017	64	12	A	46	17	Moderate	Good (a)	Green	Collect 5-10 stormwater & rainfall (24-48hrs) samples	13
City of Mandurah	Canal	MD3/410	North Port	-32.596808, 115.639226	Program	2012-2017	65	12	A	43	18	Moderate	Good (a)	Green	Collect 5-10 stormwater & rainfall (24-48hrs) samples	13
City of Mandurah	Estuary	MD3/411	Eastern Foreshore	-32.530706, 115.71955	Program	2013-2017	49	28	A	72	26	Moderate	Good (a)	Green	Collect 5-10 stormwater & rainfall (24-48hrs) samples	13
City of Mandurah	Marina	MD3/310	Marina Beach	-32.525389, 115.717531	Program	2012-2017	65	2	A	15	12	Moderate	Good (a)	Green	Collect 5-10 stormwater & rainfall (24-48hrs) samples	5
City of Mandurah	Ocean	MD3/120	Falcon Beach	-32.579771, 115.65221	Program	2012-2017	65	4	A	30	15	Low	Very Good	Green*	Annual Review	5
City of Mandurah	Ocean	MD3/155	Halls Head Parade	-32.520261, 115.705116	Program	2012-2017	65	60	B	156	37	Low	Good	Green*	Annual Review	5
City of Mandurah	Ocean	MD3/315	Town Beach	-32.519516, 115.724056	Program	2012-2017	65	26	A	253	10	Low	Very Good	Green*	Annual Review	5
City of Mandurah	Canal	MD3/280A	East Port	-32.607155, 115.646243	Reference	2012-2017	25	60	B	190	33	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/280B	East Port	-32.601145, 115.650012	Reference	2012-2017	24	110	B	220	58	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/375A	Mariners Cove	-32.554095, 115.733446	Reference	2012-2017	25	10	A	41	21	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/375B	Mariners Cove	-32.550549, 115.732398	Reference	2012-2017	20	90	B	271	46	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/401	Aztec Island	-32.542958, 115.709397	Reference	2012-2017	25	2	A	23	14	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/403	Monterey Bay	-32.537982, 115.710208	Reference	2012-2017	25	40	A	125	25	Not Avail	Not Avail	Green		5





## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
<b>Peel Region ...</b>																
City of Mandurah	Canal	MD3/404	Leslie Street Boat Ramp	-32.547972, 115.729858	Reference	2012-2017	26	100	B	520	47	Not Avail	Not Avail	Green		5
City of Mandurah	Estuary	MD3/200	Mary Street Lagoon	-32.525418, 115.708011	Reference	2012-2017	25	8	A	36	11	Not Avail	Not Avail	Green		5
City of Mandurah	Estuary	MD3/400	Southport	-32.605765, 115.636234	Reference	2012-2017	26	2	A	16	12	Not Avail	Not Avail	Green		5
City of Mandurah	Estuary	MD3/402	Henry Sutton Grove	-32.530255, 115.71314	Reference	2012-2017	25	7	A	32	10	Not Avail	Not Avail	Green		5
City of Mandurah	Marina	MD3/206	Mandurah Quay Marina	-32.559138, 115.70948	Reference	2012-2017	30	2	A	18	13	Not Avail	Not Avail	Green		5
City of Mandurah	Marina	MD3/405	Mandurah Ocean Marina	-32.523946, 115.719782	Reference	2012-2017	25	14	A	48	17	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/095	Tim`s Thicket	-32.653048, 115.61459	Reference	2011-2013	8	50	B	117	32	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/100	Melrose Boat Ramp	-32.634396, 115.618829	Reference	2011-2013	8	8	A	38	19	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/105	Pyramids Beach	-32.602718, 115.629067	Reference	2013-2017	25	20	A	66	18	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/110	Westview Parade (Avalon)	-32.592582, 115.637482	Reference	2013-2017	25	18	A	62	10	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/135	Gretel Road	-32.56693, 115.666368	Reference	2011-2013	8		A		10	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/145	Janis Street	-32.5296, 115.693566	Reference	2011-2013	8	30	A	140	10	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/150	Blue Bay Leighton Road	-32.524469, 115.696717	Reference	2012-2017	20		A		10	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/165	Orion Road	-32.50955, 115.732001	Reference	2013-2017	25	2	A	18	12	Not Avail	Not Avail	Green		5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
<b>Peel Region ...</b>																
City of Mandurah	Ocean	MD3/175	Eros Place San Remo	-32.486346, 115.743062	Reference	2013-2017	25	24	A	140	20	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/180	Madora Beach	-32.469157, 115.746114	Reference	2013-2017	25	9	A	140	10	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/287	North Port		Review	2012-2017	20	50	B	206	24	Not Avail	Not Avail	Green		5
Shire of Murray	River	MY3/002	Ravenswood Hotel - Murray River	-32.5855, 115.8268	Program	2012-2017	60	190	B	2764	85	Moderate	Good	Green	Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Shire of Murray	River	MY3/003	Murray River Bend	-32.597313, 115.833929	Program	2012-2017	60	140	B	6222	80	Moderate	Good	Green	Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Shire of Murray	River	MY3/005	Pinjarra Boat Ramp	-32.624834, 115.874457	Program	2012-2017	64	480	C	379	134	Moderate	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Murray/ DoBCA	River	MY3/007	Dwellingup Bridge	-32.7623, 116.0763	Program	2012-2017	63	40	A	68	36	Moderate	Good (a)	Green	Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Shire of Murray	River	MY3/008	Delta Drive	-32.5849, 115.7949	Program	2012-2017	60	45	B	405	36	Moderate	Good	Green	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Murray	River	MY3/009	Lucie Hunter Park	-32.585231, 115.779992	Program	2012-2017	64	65	B	102	43	Moderate	Good	Green	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Murray/ DoBCA	River	MY3/014	Baden Powell (2) Steps	-32.771706, 116.084954	Program	2012-2017	63	280	C	394	109	Low	Follow up (b)	Amber	Review Sanitary Inspection Report	13
Shire of Murray	River	MY3/020	Tatham Rd Jetty	-32.577673, 115.810278	Program	2012-2017	65	18	A	53	26	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Murray/ DoBCA	River	MY3/021	Scarp Pool	-32.764576, 115.998208	Program	2012-2017	64	55	B	98	39	Low	Good	Green	Annual Review	13
Shire of Murray	River	MY3/006	Coolup Bridge	-32.73503, 115.89988	Proposed							Not Avail	Not Avail		Review Sanitary Inspection Report	13





## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
<b>Peel Region ...</b>																
Shire of Murray	Inlet	MY3/018	Coopers Mill	-32.575917, 115.765693	Reference	2012-2017	60	65	B	846	41	Low	Good	Green		
Shire of Waroona/ Water Corp	Lake	WR3/001	Drakesbrook Dam / Lake Moyanup	-32.858754, 115.951325	Program	2012-2017	14	210	C	294	87	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
Shire of Waroona/ Water Corp	Lake	WR3/002	Waroona Dam / Lake Navarino	-32.851049, 115.990144	Program	2012-2017	11	70	B	246	35	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
<b>South West Region</b>																
City of Bunbury	Drain	BC3/023	Meredith Creek Compensation Basin	-33.328163, 115.647122	Point Source	Not Available					N/A	Not Avail	Not Avail	N/A		
City of Bunbury	Drain	BC3/028	Queens Gardens	-33.326003, 115.641442	Point Source	Not Available					N/A	Not Avail	Not Avail	N/A		
City of Bunbury	Drain	BC3/029	Queens Pump	-33.325747, 115.641875	Point Source	Not Available					N/A	Not Avail	Not Avail	N/A		
City of Bunbury	Drain	BC3/030	Blair St Canal	-33.330719, 115.642928	Point Source	Not Available					N/A	Not Avail	Not Avail	N/A		
City of Bunbury	Estuary	BC3/003	Rowing Club	-33.324674, 115.64231	Point Source	Not Available									Provide DOH Sanitary Inspection Report	5
City of Bunbury	Harbour	BC3/001	Jetty Bath West	-33.31558, 115.63829	Program	2012-2017	55	80	B	232	42	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Bunbury	Ocean	BC3/012	Koombana Beach	-33.31949, 115.64565	Program	2012-2017	53	18	A	54	22	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Bunbury	Ocean	BC3/017	Surf Club Beach	-33.32742, 115.62927	Program	2012-2017	54	2	A	14	11	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	5
City of Bunbury	Ocean	BC3/018	Hungry Hollow	-33.33371, 115.62703	Program	2012-2017	55	18	A	58	17	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Bunbury	Ocean	BC3/025	Ski Beach	-33.319, 115.64005	Program	2012-2017	53	9	A	40	15	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
<b>South West Region ...</b>																
City of Bunbury	Estuary	BC3/002	Estuary Plug	-33.320967, 115.641159	Reference											
City of Bunbury	Estuary	BC3/004	Bunbury Yacht Club	-33.326464, 115.64709	Reference											
City of Bunbury	Estuary	BC3/005	Meredith Creek	-33.327144, 115.648331	Reference											
City of Bunbury	Estuary	BC3/006	Parade Hotel	-33.327536, 115.654558	Reference											
City of Bunbury	Estuary	BC3/007	Sofilas	-33.328099, 115.659039	Reference											
City of Bunbury	Estuary	BC3/010	Turkey Point	-33.306184, 115.674212	Reference											
City of Bunbury	Estuary	BC3/026	Sykes Foreshore	-33.32333, 115.643395	Reference											
City of Bunbury	Estuary	BC3/027	Canoe Launch	-33.321661, 115.639896	Reference											
City of Bunbury	Harbour	BC3/021	Harbour East	-33.31376, 115.640622	Reference											
City of Bunbury	Harbour	BC3/022	Harbour West	-33.311596, 115.63806	Reference											
City of Bunbury	River	BC3/008	Preston River	-33.326701, 115.671439	Reference											
City of Bunbury	River	BC3/009	Collie River	-33.309425, 115.696352	Reference											



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018	
<b>South West Region ...</b>																	
City of Busselton	Creek	BN3/022	Margaret St - Creek	-33.651729, 115.32365	Point Source	2014-2017	30	880	D	887	242	N/A	Not Avail	Red	N/A	5	
City of Busselton	Creek	BN3/027	Forth St - Creek	-33.65705, 115.24761	Point Source	2014-2017	29	160	B	260	75	N/A	Not Avail	Green	N/A	5	
City of Busselton	Drain	BN3/021	Margaret St - Drain	-33.65324, 115.32367	Point Source	2014-2017	30	660	D	119680	1902	N/A	Not Avail	Red	N/A	5	
City of Busselton	Ocean	BN3/023	Margaret Street Beach (Site 8)	-33.650749, 115.324495	Program	2012-2017	55	160	B	465	79	Moderate	Good	Green	Collect 5-10 rainfall (24-48hrs) & riverine/ drain samples	13	
City of Busselton	Ocean	BN3/024	Scout Beach (Site 6)	-33.655705, 115.234292	Program	2012-2017	55	130	B	14773	61	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13	
City of Busselton	Ocean	BN3/025	Forth Street Beach (Site 7)	-33.656216, 115.248267	Program	2012-2017	54	140	B	970	73	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13	
City of Busselton	Ocean	BN3/028	Busselton Jetty Ocean 9	-33.644157, 115.344108	Program	2012-2017	53	560	D	59608	1135	Moderate	Poor	Red	Collect 5-10 rainfall (within 24hrs) samples	13	
City of Busselton	Creek	BN3/043	Wonnerup Floodgate	-33.619346, 115.41385	Reference	2015-2017	27	28	A	70	28	Not Avail	Not Avail	Green		5	
City of Busselton	Creek	BN3/044	Wonnerup Inlet Road Bridge	-33.61663, 115.420272	Reference	2015-2017	27	840	D	4009	487	Not Avail	Not Avail	Red		5	
City of Busselton	Marina	BN3/351	Port Geographe - Inlet Pool North	-33.629533, 115.390131	Reference	Not Available											
City of Busselton	Marina	BN3/355	Port Geographe - Swimming Lagoon	-33.629892, 115.389677	Reference	2015-2017	16	30	A	121	13	Not Avail	Not Avail	Green		5	
City of Busselton	Marina	BN3/356	Mainsail Beach	-33.632342, 115.396762	Reference	Not Available											
City of Busselton	Marina	BN3/357	Port Geographe Boat Ramp	-33.630338, 115.395292	Reference	Not Available											
City of Busselton	Ocean	BN3/045	Wonnerup Inlet Ocean Mouth	-33.610202, 115.423175	Reference	2015-2017	27	90	B	145	51	Not Avail	Not Avail	Green		5	

## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018
<b>South West Region ...</b>																
Shire of Augusta-Margaret River	Inlet	AM3/023	Hardy Inlet - Turner Caravan Park	-34.32322, 115.16486	Program	2012-2017	68	440	C	953	186	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	Ocean	AM3/012	Gnarabup Beach (Jetty)	-33.99016, 114.9908	Program	2012-2017	67	65	B	286	31	Low	Good	Green*	Annual Review	5
Shire of Augusta-Margaret River/ DoBCA	Ocean	AM3/014	Gracetown Beach	-33.86435, 114.98647	Program	2012-2017	68	8	A	38	15	Low	Very Good	Green*	Annual Review	5
Shire of Augusta-Margaret River	Ocean	AM3/016	Flinders Bay - Redman Brook	-34.34317, 115.16872	Program	2012-2017	68	9	A	40	12	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) & riverine samples	5
Shire of Augusta-Margaret River	River	AM3/001	Margaret River - Canoe Landing	-33.96951, 114.98891	Program	2012-2017	65	135	B	317	68	Low	Good	Green*	Annual Review	5
Shire of Augusta-Margaret River	River	AM3/006	Margaret River - Barrett St Weir	-33.94814, 115.08243	Program	2012-2017	67	110	B	161	57	High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Augusta-Margaret River	River	AM3/044	Margaret River - Rendall CI Weir	-33.949358, 115.086087	Program	2014-2017	40	28	A	76	25	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Augusta-Margaret River	River	AM3/002	Margaret River - Rivermouth	-33.971092, 114.987313	Review	2013-2017	41	140	B	202	66	Moderate	Good	Green	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Capel	Ocean	CP3/001	Forrest Beach	-33.57244, 115.46048	Program	2012-2017	36	920	D	4945	570	Moderate	Poor	Red	Collect 5-10 rainfall (within 24-hrs) samples	13
Shire of Capel	Ocean	CP3/002	Peppermint Grove Beach	-33.527373, 115.504204	Program	2012-2017	36	55	B	700	29	Moderate	Good	Green	Collect 5-10 rainfall (within 24-hrs) samples	13
Shire of Capel	Ocean	CP3/003	Minninup Beach	-33.451544, 115.575228	Program	2012-2017	36	230	C	784	117	Moderate	Poor	Red	Collect 5-10 rainfall (within 24-hrs) samples	13
Shire of Capel	Ocean	CP3/004	Dalyellup Beach	-33.404978, 115.600615	Program	2012-2017	35	95	B	739	43	Moderate	Good	Green	Collect 5-10 rainfall (within 24-hrs) samples	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018				
<b>South West Region ...</b>																				
Shire of Capel	River	CP3/005	Preston River - Boyanup	-33.478692, 115.733701	Program	2012-2017	37	1950	D	1443	257	High	Very Poor	Red*	Recommend erect perm warning sign	5				
Shire of Capel	River	CP3/006	Capel River - Mallokup Bridge	-33.519698, 115.537251	Program	2012-2017	37	210	C	332	89	High	Poor	Red	Collect 5-10 upstream Riverine + regular site samples	13				
Shire of Capel	Ocean	CP3/008	North Dalyellup Beach	-33.397131, 115.603824	New	Not Available										Provide DOH Sanitary Inspection Report	13			
Shire of Capel	Ocean	CP3/007	Water Corp Dalyellup Beach	-33.382122, 115.609281	Reference	Not Available										Provide DOH Sanitary Inspection Report	5			
Shire of Collie	Lake	CI3/004	Stockton Lake	-33.382218, 116.225014	New	2016-2017	14		A		10	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13				
Shire of Collie/ DoPLH	Lake	CI3/003	Black Diamond Recreational Water Area	-33.341823, 116.095387	Program	2015-2017	25	2	A	14	11	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13				
Shire of Collie/ DoBCA	Reservoir	CI3/001	Potters Gorge - Wellington Dam	-33.390301, 115.983908	Program	Not Available										Low	Not Avail	Green	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Collie/ DoBCA	River	CI3/002	Honeymoon Pool - Preston River	-33.379581, 115.938206	Program	2015-2017	10	30	A	63	32	Moderate	Not Avail	Amber	Collect 5-10 rainfall (24-48hrs) samples	13				
Shire of Collie	River	CI3/005	Minninup Pool - Front Parking A	-33.376853, 116.138084	Program	2016-2017	11	2950	D	17053	2040	Not Avail	Not Avail	Red	Provide DOH Sanitary Inspection Report	13				
Shire of Collie	River	CI3/006	Minninup Pool - Stone Stairwell	-33.377038, 116.137753	Reference	2016-2017	10	175	B	336	81	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13				
Shire of Donnybrook-Balingup	River	DB3/013	Preston River - Donnybrook Amphitheatre	-33.575903, 115.826496	Reference	Not Available														
Shire of Donnybrook-Balingup	River	DB3/014	Preston River - Footbridge	-33.57437, 115.825772	Reference	Not Available														



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018	
<b>South West Region ...</b>																	
Shire of Harvey	Lake	HA3/027	Lake Brockman Boat Ramp	-33.002994, 115.971344	Program	2014-2017	26	14	A	51	19	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) & riverine samples	13	
Shire of Harvey	Ocean	HA3/020	Myalup Beach	-33.103452, 115.686984	Program	2012-2017	36	12	A	140	10	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13	
Shire of Harvey	Ocean	HA3/021	Binningup Beach	-33.148933, 115.685686	Program	2012-2017	36	40	A	140	10	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13	
Shire of Harvey	Reservoir	HA3/026	Harvey Dam Boat Ramp	-33.081085, 115.953328	Program	2014-2017	26	26	A	140	30	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) samples	13	
Shire of Mangimup/ Private	Reservoir	MJ3/1811	Fonty's Pool - SE Cnr Pool (near outlet)	-34.289472, 116.065229	Proposed	Not Available										Provide DOH Sanitary Inspection Report	13
Shire of Nannup/ DoBCA	River	NA3/001	Barrabup Pool - Platform	-33.944293, 115.691058	Proposed	Not Available											13
Shire of Nannup/ DoBCA	River	NA3/002	Workers Pool - Steps	-33.953875, 115.686802	Proposed	Not Available											13
<b>Wheatbelt Region</b>																	
Shire of Dandaragan/ DoT	Harbour	DA3/006	Jurien Boat Harbour Beach (West)	-30.291149, 115.044075	Program	2012-2017	35	32	A	80	27	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13	
Shire of Dandaragan/ DoT	Harbour	DA3/007	Jurien Boat Harbour Beach (East)	-30.290526, 115.045607	Program	2012-2017	33	10	A	140	30	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13	
Shire of Dandaragan	Ocean	DA3/013	Dobbyn Park Beach	-30.301367, 115.03697	Program	2012-2017	34	4	A	30	17	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13	
Shire of Dandaragan	Ocean	DA3/015	Cervantes - Swimming Beach	-30.495617, 115.065755	Program	2012-2017	32	300	C	7203	268	Moderate	Poor	Red	Collect 5-10 effluent discharge samples	13	
Shire of Dandaragan/ DoT	Ocean	DA3/016	Cervantes - Jetty/Boat Ramp	-30.491262, 115.068565	Program	2012-2017	32	2	A	22	15	Moderate	Good (a)	Green	Collect 5-10 effluent discharge samples	13	





## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2017 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	LGA/ MA SAC Status Actions	Min No. Samples Rqd 2017-2018	
<b>Wheatbelt Region</b>																	
Shire of Gingin	River	GG3/001	Moore River - Mouth Beach	-31.352224, 115.499251	New	2013-2017	10	2	A	19	13	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13	
Shire of Gingin	River	GG3/002	Moore River - Caravan Park	-31.351037, 115.500438	New	2013-2017	10	280	C	782	134	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13	
Shire of Gingin	River	GG3/003	Moore River - Boat Ramp	-31.351811, 115.502752	New	2013-2017	10	185	B	569	93	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13	
Shire of Gingin	River	GG3/010	Moore River Desert Boardwalk	-31.01071, 115.3279	New	2013-2017	10	200	B	300	86	Not Avail	N/A	Green	Provide DOH Sanitary Inspection Report	13	
Shire of Gingin	Ocean	GG3/011	Lancelin Grace Darling Park	-31.0246, 115.3282	Proposed	Not Available											
Shire of Gingin	Ocean	GG3/012	Lancelin Harold Park	-31.010732, 115.327557	Proposed	Not Available											
Shire of West Arthur/ DoT	Lake	AW3/001	Lake Towerrinning - Jetty 1	-33.583888, 116.791518	Program	2012-2017	30	1000	D	8582	784	Moderate	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13	
Shire of West Arthur	Lake	AW3/002	Lake Towerrinning - Caravan Park	-33.588671, 116.78572	Program	2013-2017	22	1150	D	2307	438	Not Avail	Not Avail	Red	Provide DOH Sanitary Inspection Report	13	