



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
ALBANY	AC3/007	Emu Beach - Oyster Harbour							Outstanding		Provide DoH Sanitary Inspection Report	Not Avail		13
ALBANY	AC3/008	Ellen Cove (Jetty) - Middleton Beach							Outstanding		Provide DoH Sanitary Inspection Report	Not Avail		13
ALBANY	AC3/009	Boatshed Beach - Princess Royal Harbour							Outstanding		Provide DoH Sanitary Inspection Report	Not Avail		13
ALBANY	AC3/010	Frenchman Bay							Outstanding		Provide DoH Sanitary Inspection Report	Not Avail		13
AUGUSTA-MARGARET RIVER	AM3/023	Hardy Inlet (Turner Caravan Park)	2009-2014	64	330	C	574	134	Outstanding		Provide DoH Sanitary Inspection Report	Fair (a)	Amber	13
AUGUSTA-MARGARET RIVER	AM3/012	Gnarabup Beach (Jetty)	2009-2014	64	190	B	1405	107	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
AUGUSTA-MARGARET RIVER	AM3/014	Gracetown Beach	2009-2014	65	75	B	321	38	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
AUGUSTA-MARGARET RIVER	AM3/016	Flinders Bay (Redman Brook)	2009-2014	65	38	A	115	23	Moderate	Rainfall & Riverine	Collect 10 rainfall & riverine samples	Good (a)	Green	13



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
AUGUSTA-MARGARET RIVER	AM3/001	Margaret River (Canoe Landing)	2009-2014	64	280	C	467	115	Outstanding		Provide DoH Sanitary Inspection Report	Fair (a)	Amber	13
AUGUSTA-MARGARET RIVER	AM3/006	Margaret River - Barrett St Weir	2009-2014	63	180	B	247	78	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
BUNBURY	BC3/001	Jetty Bath West	2009-2014	63	65	B	271	32	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	15
BUNBURY	BC3/012	Koombana Beach	2009-2014	61	40	A	108	29	Moderate - F/up	Rainfall	Provide DoH Sanitary Inspection Report	Good (a)	Green	16
BUNBURY	BC3/017	Surf Club Beach	2009-2014	63	6	A	32	11	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
BUNBURY	BC3/018	Hungry Hollow	2009-2014	63	6	A	33	14	Moderate - F/up	Rainfall	Provide DoH Sanitary Inspection Report	Good (a)	Green	5
BUNBURY	BC3/025	Ski Beach	2009-2014	62	22	A	71	15	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	16
BUSSELTON	BN3/023	Margaret Street Beach (Site 8)	2009-2014	53	150	B	450	74	Moderate	Rainfall & Riverine	Collect 10 rainfall (24-48hrs) & riverine samples	Good	Green	13
BUSSELTON	BN3/024	Scout Beach (Site 6)	2009-2014	55	45	B	145	27	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
BUSSELTON	BN3/025	Forth Street Beach (Site 7)	2009-2014	54	110	B	402	55	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
BUSSELTON	BN3/028	Busselton Jetty Ocean 9	2009-2014	50	310	C	604	130	Moderate - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
CAPEL	CP3/001	Forrest Beach	2009-2014	51	560	D	3265	349	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
CAPEL	CP3/002	Peppermint Grove Beach	2009-2014	51	50	B	274	17	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
CAPEL	CP3/003	Minningup Beach	2009-2014	49	125	B	248	63	Moderate	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
CAPEL	CP3/004	Dalyellup Beach	2009-2014	49	22	A	70	15	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
CAPEL	CP3/005	Preston River (Boyanup)	2010-2014	39	2950	D	2293	607	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Very Poor	Red	5
CAPEL	CP3/006	Capel River (Mallokup Bridge)	2010-2014	39	560	D	1127	225	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Very Poor	Red	13
CARNARVON	CN3/001	Carnarvon Town Beach	2009-2014	54	200	B	544	97	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
CARNARVON	CN3/002	Carnarvon Town Beach (2)	2009-2014	27	2	A	15	11	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
CARNARVON	CN3/003	Facsine Beach	2009-2014	45	38	A	83	32	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
CARNARVON	CN3/004	Before Yacht Club	2009-2014	36	95	B	700	20	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
CARNARVON	CN3/005	Yacht Club	2013-2014	19	24	A	74	19	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
CARNARVON	CN3/006	Yacht Club Marina	2013-2014	19	20	A	52	28	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
CARNARVON	CN3/041	Northwater DB Drive	2011-2014	31	135	B	311	68	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
CARNARVON	CN3/042	Northwater Jaaga	2011-2014	25	105	B	810	48	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
CARNARVON	CN3/043	Boat Harbour Snapper Jetty	2011-2014	34	2	A	22	16	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
CARNARVON	CN3/044	Boat Harbour Wharf	2011-2014	34	6	A	35	20	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
CARNARVON	CN3/045	Fascine Jetty	2011-2014	35	12	A	43	23	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
CARNARVON	CN3/046	Pelican Point Beach	2013-2014	20	2	A	21	12	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
CARNARVON	CN3/047	Chinamans Pool	2013-2014	19	460	C	392	134	Outstanding		Provide DoH Sanitary Inspection Report	Fair (a)	Amber	13
DANDARAGAN	DA3/006	Jurien Boat Harbour Beach (West)	2009-2014	40	50	B	158	30	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	13
DANDARAGAN	DA3/007	Jurien Boat Harbour Beach (East)	2009-2014	41	12	A	46	15	Moderate - F/up	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	13
DANDARAGAN	DA3/013	Dobbyn Park Beach	2009-2014	39	22	A	70	19	Moderate - F/up	Rainfall	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	13
DANDARAGAN	DA3/015	Cervantes - Swimming Beach	2012-2014	9	210	C	351	91	Outstanding		Provide DoH Sanitary Inspection Report	Fair (a)	Amber	13
DANDARAGAN	DA3/016	Cervantes - Jetty/Boat Ramp	2012-2014	9	3	A	29	18	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
DENMARK	DK3/052	(Creek) Inlet Drive Bridge 3	2012-2013	13	520	D	586	164	Not Applicable		Provide DoH Sanitary Inspection Report	Poor	Red	0
DENMARK	DK3/050	Wilson Inlet - Ocean Beach Caravan Park	2012-2014	26	30	A	101	16	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
DENMARK	DK3/051	Wilson Inlet - Yacht Club Gazebo 2	2012-2014	34	180	B	609	91	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
DENMARK	DK3/053	Wilson Inlet - Rivermouth Caravan Park 4	2012-2014	34	1050	D	4228	568	Outstanding		Provide DoH Sanitary Inspection Report	Very Poor	Red	13
DENMARK	DK3/055	Wilson Inlet - Springdale Beach 6	2012-2013	25	100	B	333	52	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
DENMARK	DK3/025	Peaceful Bay - Ocean/Drain	2011-2014	17	36	A	108	23	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
DENMARK	DK3/025A	Peaceful Bay - Ocean (South)	2011-2014	16	140	B	700	10	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
DENMARK	DK3/025B	Peaceful Bay - Ocean North of DK3/025	2010-2014	23	5	A	31	14	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	5
DENMARK	DK3/054	Denmark River - Berridge Park 5	2012-2014	34	1150	D	1795	383	Outstanding		Provide DoH Sanitary Inspection Report	Very Poor	Red	13



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
ESPERANCE	ES3/030	Bandy Creek Harbour	2011-2014	40	520	D	2045	277	Moderate - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
ESPERANCE	ES3/031	James St Groyne	2011-2014	39	135	B	377	69	Moderate - F/up	Stormwater	Provide DoH stormwater drain monitoring results	Good (a)	Green	13
ESPERANCE	ES3/032	Port Authority Beach	2011-2014	39	95	B	171	52	Moderate	Stormwater	Provide DoH stormwater drain monitoring results	Good (a)	Green	13
EXMOUTH	EX3/050	Small Boat Harbour	2009-2014	39	60	B	172	36	Outstanding			Good	Green	13
EXMOUTH	EX3/051	Exmouth Town Beach	2009-2014	40	90	B	177	50	Outstanding			Good	Green	13
EXMOUTH	EX3/057	Marina - Canal	2009-2014	43	9	A	39	15	Outstanding			Very Good	Green	13



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
GINGIN	GG3/001	Moore River Mouth Beach							Outstanding		Provide DoH Sanitary Inspection Report	Not Avail		13
GINGIN	GG3/002	Moore River Caravan Park Beach							Outstanding		Provide DoH Sanitary Inspection Report	Not Avail		14
GINGIN	GG3/003	Moore River Boat Ramp							Outstanding		Provide DoH Sanitary Inspection Report	Not Avail		15
GINGIN	GG3/010	Moore River Desert (Boardwalk)							Outstanding		Provide DoH Sanitary Inspection Report	Not Avail		16
GREATER GERALDTON	GE3/001	Town Beach Jetty	2009-2014	51	90	B	3053	28	High - F/up	Stormwater	Collect 5-10 stormwater drain samples	Fair (a)	Amber	13
GREATER GERALDTON	GE3/003	Point Moore North	2009-2014	50	90	B	261	46	Moderate - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
GREATER GERALDTON	GE3/005	Separation Point	2009-2014	45	140	B	306	69	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	13
GREATER GERALDTON	GE3/006	Back Beach	2009-2014	48	32	A	114	18	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	13
GREATER GERALDTON	GE3/008	Marina North	2009-2014	51	26	A	140	10	Moderate - F/up	Stormwater	Provide DoH stormwater drain monitoring results	Good (a)	Green	13
GREATER GERALDTON	GE3/010	Saint Georges Beach	2009-2014	52	55	B	700	30	Moderate - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
GREATER GERALDTON	GE3/012	Sunset Beach Triton Place	2011-2014	26	105	B	474	52	Outstanding		Provide DoH Sanitary Inspection Report	Not Avail	Green	13
GREATER GERALDTON	GE3/021	Pages Beach North	2009-2014	50	280	C	694	129	Moderate - F/up	Stormwater	Provide DoH stormwater drain monitoring results	Poor	Red	13



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
GREATER GERALDTON	GE3/022	Tarcoola Beach	2009-2014	48	115	B	557	57	Very Low		Provide DoH stormwater drain monitoring results	Good	Green	13
GREATER GERALDTON	GE3/023	Greenough Beach	2009-2014	45	30	A	97	20	Moderate - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Good	Green	13
GREATER GERALDTON	GE3/026	Drummonds Cove	2009-2014	39	30	A	80	25	Moderate - F/up	Rainfall	Collect 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
GREATER GERALDTON	GE3/024	Greenough River Mouth	2009-2014	48	110	B	700	41	High - F/up	Rainfall	Provide DoH Sanitary Inspection Report	Fair (a)	Red	13
GREATER GERALDTON	GE3/025	Ellendale Pool	2009-2014	48	320	C	363	113	High - F/up	Rainfall	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
HARVEY	HA3/026	Harvey Dam Boat Ramp							Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Fair (a)	Amber	13
HARVEY	HA3/027	Lake Brockman Boat Ramp							Moderate - F/up	Rainfall & Riverine	Collect min 5-10 rainfall (24-48hrs) & riverine samples	Fair (a)	Amber	13
HARVEY	HA3/020	Myalup Beach	2009-2014	22	12	A	140	10	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
HARVEY	HA3/021	Binningup Beach	2009-2014	22	60	B	700	10	Moderate	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green	13
IRWIN	IR3/001	Nunns Pool	2009-2014	21	10	A	43	18	Moderate - F/up	Rainfall & Riverine	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
IRWIN	IR3/060	South Beach	2009-2014	21	80	B	390	36	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
IRWIN	IR3/070	Grannie's Beach	2009-2014	22	145	B	1843	78	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
IRWIN	IR3/080	Marina (Boat Ramp)	2009-2014	21		A		10	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13
MANDURAH	MD3/105	Pyramids Beach	2008-2014	26	24	A	79	15				Very Good	Green	
MANDURAH	MD3/110	Westview Parade (Avalon)	2008-2014	26	45	B	151	25				Good	Green	
MANDURAH	MD3/120	Falcon Beach	2009-2014	82	7	A	36	16	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	5
MANDURAH	MD3/155	Halls Head Parade	2009-2014	84	36	A	104	25	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
MANDURAH	MD3/165	Orion Road	2008-2014	25	6	A	140	10				Very Good	Green	
MANDURAH	MD3/175	Eros Place San Remo	2008-2014	25	6	A	32	13				Very Good	Green	
MANDURAH	MD3/180	Madora Beach	2008-2014	25	32	A	178	10				Very Good	Green	
MANDURAH	MD3/200	Mary Street Lagoon	2008-2014	33	16	A	52	18				Very Good	Green	
MANDURAH	MD3/206	Mandurah Quay Marina	2008-2014	30	4	A	30	18				Very Good	Green	
MANDURAH	MD3/280A	East Port	2008-2014	32	40	A	107	28				Very Good	Green	



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
MANDURAH	MD3/280B	East Port	2008-2014	31	38	A	86	32				Very Good	Green	
MANDURAH	MD3/310	Marina Beach	2009-2014	82	3	A	26	14	Moderate - F/up	Rainfall & Stormwater	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green	5
MANDURAH	MD3/315	Town Beach	2009-2014	81	12	A	48	15	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
MANDURAH	MD3/330	Hall Park	2009-2014	81	28	A	70	27	Moderate - F/up	Rainfall & Stormwater	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green	13
MANDURAH	MD3/375A	Mariners Cove	2008-2014	30	2	A	17	14				Very Good	Green	
MANDURAH	MD3/400	Southport	2008-2014	27	3	A	24	12				Very Good	Green	
MANDURAH	MD3/401	Aztec Island	2008-2014	32	2	A	24	14				Very Good	Green	
MANDURAH	MD3/402	Henry Sutton Grove	2008-2014	32	16	A	140	20				Very Good	Green	
MANDURAH	MD3/403	Montreal Bay	2008-2014	32	2	A	20	13				Very Good	Green	
MANDURAH	MD3/404	Leslie Street Boat Ramp	2008-2014	30	6	A	33	17				Very Good	Green	
MANDURAH	MD3/405	Mandurah Ocean Marina	2008-2014	19	2	A	22	10				Very Good	Green	
MURRAY	MY3/018	Coopers Mill	2009-2014	56	38	A	75	34	Outstanding		Provide DoH Sanitary Inspection Report	Very Good	Green	13



Regional Recreational Waters Bacterial (Enterococci) Sampling Program Site Status Overview (October 2014)

LGA	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	SAC Key Factors	SAC Status Comments	Provisional Class	Provisional Colour	Min No. LGA Samples Required 2014-2015
MURRAY	MY3/002	Ravenswood Hotel - Murray River	2009-2014	70	250	C	316	98	Very High - F/up	Animals	Review Sanitary Inspection Category	Poor	Red	14
MURRAY	MY3/003	Murray River Bend	2009-2014	69	240	C	7534	120	Very High - F/up	Animals	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
MURRAY	MY3/005	Pinjarra Boat Ramp	2009-2014	74	760	D	757	213	Very High	Septics Tanks & Animals	Follow-up Re: Management Actions	Very Poor	Red	5
MURRAY	MY3/007	Dwellingup Bridge	2009-2014	73	155	B	137	64	Very High - F/up	Animals	Collect 10 rainfall (24-48hrs) samples	Fair (a)	Amber	13
MURRAY	MY3/008	Delta Drive	2009-2014	69	150	B	14342	52	Very High - F/up	Animals	Collect 10 rainfall (24-48hrs) samples	Fair (a)	Amber	13
MURRAY	MY3/009	Lucie Hunter Park	2009-2014	72	240	C	6215	188	Very High - F/up	Animals	Collect 10 rainfall (24-48hrs) samples	Poor	Red	13
MURRAY	MY3/014	Baden Powell (2) Steps	2009-2014	73	640	D	870	212	Outstanding		Provide DoH Sanitary Inspection Report	Very Poor	Red	13
MURRAY	MY3/020	The Clansman	2009-2014	38	85	B	169	49	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
MURRAY	MY3/021	Scarp Pool	2009-2014	38	60	B	101	43	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
WAROONA	WR3/001	Drakesbrook Dam / Lake Moyanup							Outstanding		Provide DoH Sanitary Inspection Report	Not Avail		13
WAROONA	WR3/002	Waroona Dam / Lake Navarino	2008-2014	14	170	B	1223	94	Outstanding		Provide DoH Sanitary Inspection Report	Good	Green	13
WEST ARTHUR	AW3/001	Lake Towerrinning - Jetty 1	2010-2014	19	1400	D	252477	5794	Moderate - F/up	Rainfall	Collect min 5-10 rainfall (24-48hrs) samples	Poor	Red	13